SURVEY & REMONUMENTATION

JUN 0 2 1994

For corners in

Private Claims ___

OGEMAW COUNTY REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

·····REC				
OGEMAW	CO.	UNTY,	И:	
TRER	2	DATE	21	1

, 0, 00,,,,0,0			
OGEMAW	Located In:	Corner Code ##	
(County)			
1. Public Land Survey	T R T21N R _3E	м-6	
•	T R		

93 DEC 29 PH 2: 56

Wands Mugil

Register of Deeds Stamp & File Number

	(County)		
1.	Public Land Survey	T R T21N R _3E	м-6
		T R T R	
2.	Property Controlling in Section	S T R S T R	
3.	Miscellaneous Property in Sec.	S T R S T R	
4.	Lot No ,	Recorded Plat	

TIMOTHY L. LAPHAM field survey on December . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

- A. Description of original monument and accessories and/or subsequent restoration:
- M-6: 1838 CLASON; POST; W. PINE 8" S62W 43 LKS; S. MAPLE 9" N56W 39 LKS 12/19/1974 N. CALDWELL; LCRC 1-155; 1" PIPE IN LINE WITH FENCE EAST 12/23/1974 N. CALDWELL; NO WITNESSES 5/23/1989 T. LAPHAM; UTILIZED IN ESTABLISHING CENTER OF SECTION 13, NO WITNESSES; DISTANCES N 2616.65, S 2620.09 TO RICHARDSON CORNER 2633 +/- TO HENNING CORNER
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-6: FOUND 1/2" REROD OVER LARGE METAL OBJECT 3' +/- DEEP IN LINE WITH FENCE TO EAST; MATCHED DISTANCES IN 12/23/1974 AND 5/23/1989 SURVEYS THIS CORNER ESTABLISHED IN OGEMAW COUNTY REMONUMENTATION PROGRAM. SEE DOSSIER FOR DETAILED REPORT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-6: SET 5/8"X36" REROD WITH 3" OGEMAW CO. MONUMENT CAP IN MON. BOX

AZ 92° 52.23' SPIKE IN S FACE UTILITY POLE

AZ 56° 38.12' SPIKE IN NW FACE SQUARE FENCE POST AZ 290° 53.89' SPIKE IN SW FACE UTILITY POLE AZ 210° 80.98' SPIKE IN NW FACE UTILITY POLE



Signed by

27595 Surveyor's Michigan License No. ___

_ Date _/

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28 REVISED MAY 14,

REVISED JAN..