

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Ogemaw (County)	Located In	Corner Code #
1. Public Land Survey	T <u>23 N</u> R <u>1 E</u>	<u>K-12</u>
	<u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on July 6, 2000 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-12 G.L.O. -James H. Mullett D.S., 1846
Set quarter section post
Wit: Black Oak 6" S61°W 53 Links
Black Oak 4" N82°E 62 Links

Marcus Schaaf RLS# 3104, set pipe in concrete for corner.
No witnesses or date given

James Richardson RLS #2527, found 2" pipe for corner and used it for his plat of Hidden Hills, no date or witnesses given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-12 Found 2" iron pipe

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-12 Found 2" iron pipe
Wit: 3" Oak N51°E 26.39'
12" Oak S41°E 24.20'
7" Red Pine S74°W 48.38'
14" Oak N48°W 26.68'
Carsonite Post East 16.5'±
Intersection of trail roads N-S and W



Signed by: Carl T. Kiiskila
Surveyor's Michigan License No.: 33981

Date: 12-4-00