

Attach to: T23N R4E A-2 Seg #1 MRD

SURVEY & REMONUMENTATION

MAY 03 1995 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in OGEMAW (County)

COMMISSION

Located In:

Corner Code #

- 1. Public Land Survey T 23N R 3E M-2
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R

LIBER 2 PAGE 262 STATE OF MICHIGAN OGEMAW COUNTY RECORDED

3 JAN 95 9:35 A.M.

WANDA MUZIK REGISTER OF DEEDS Register of Deeds Stamp & File Number

- 4. Lot No. Recorded Plat
5. Private Claims

Grid table with columns A-K and rows 2-13, containing numbers 6-35.

I, Timothy L. Lapham, in a field survey on December, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- M-2: GLO CLASON 1838, SET POST
W. PINE 22" S31W 26LKS
Y. PINE 14" N47W 71LKS
CALDWELL SURVEY 1-13 JULY 1971, NO COR MAT, NO WITS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- M-2: FOUND UNLEGIBLE CAPPED IRON
DISTANCE NORTH AND SOUTH AGREE WITH GLO
ACCEPTED FOUND CORNER AS BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER
CORNER APPROVED AT PEER REVIEW MEETING HELD ON DECEMBER 21, 1994
SEE DOSSIER FOR ADDITIONAL INFORMATION

APPROVED BY PEER REVIEW 12-21-94 DATE P.A. 345 of 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- M-2: SET 5/8"x36" ROD WITH 3-1/4" ALUMINUM OGEMAW REMON CAP
N64E 30.45' NAIL IN TRIPLE 10" PIN OAK
S05W 9.43' NAIL IN TWIN 8" OAK
N65W 25.81' NAIL IN 10" PIN OAK
N08W 47.89' NAIL IN 12" PIN OAK

Signed by [Signature] Surveyor's Michigan License No. 27595

Date 12/29/94

SURVEY & REMONUMENTATION

MAY 05 1997

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

4 corners in **COMMISSION**

OGEMAW (County)	Located In:	Corner Code #
Public Land Survey	T 23N R 4E	A-1
	T 23N R 4E	A-2
	T 23N R 4E	A-3
Property Controlling In Section	S T 23N R 3E	M-1 A.S. 1/3/99
Miscellaneous	S T 23N R 3E	M-2 A.S. 1/3/99
Property in Sec.	S T R	M-3 A.S. 1/3/99

LIBER 3 PAGE 01

STATE OF MICHIGAN
 OGEMAW COUNTY
 RECORDED

20 APR 95 10:19 A.M.

WANDA MUZIK
 Register of Deeds Stamp & File Number
 REGISTER OF DEEDS

Lot No. _____, Recorded Plat _____
 Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	16		17		18		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Timothy L. Lapham, in a field survey on December, 19 94, hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

DTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
- 1: COMMON CORNER WITH M-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994
 - 2: COMMON CORNER WITH M-2, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994
 - 3: COMMON CORNER WITH M-3, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1: COMMON CORNER WITH M-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
 - A-2: COMMON CORNER WITH M-2, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
 - A-3: COMMON CORNER WITH M-3, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1: COMMON CORNER WITH M-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
 - A-2: COMMON CORNER WITH M-2, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
 - A-3: COMMON CORNER WITH M-3, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.

Signed by *Timothy L. Lapham*

Date 4/20/95

Surveyor's Michigan License No. 27595

