

SURVEY &
REMONUMENTATION

Attach to: T 23N R 4E A-5 Seg. #1 MRD

MAY 03 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
OGEMAW

	(County)	Located in:	Corner Code #
1. Public Land Survey		T <u>23N</u> R <u>3E</u>	<u>M-5</u>
		T _____ R _____	_____
		T _____ R _____	_____
		T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____		<u>Seg. #1</u>
	S _____ T _____ R _____		_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____		_____
	S _____ T _____ R _____		_____
4. Lot No. _____, Recorded Plat _____			
5. Private Claims _____			

LIBER 2 PAGE 265
STATE OF MICHIGAN
OGEMAW COUNTY
RECORDED
3 JAN 95 9:36 A.M.
WANDA MUZIK
Register of Deeds Stamp #108

A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2						
3											
4	7	8	9	10	11						
5											
6	18	17	16	15	14						
7											
8	19	20	21	22	23						
9											
10	30	29	28	27	26						
11											
12	31	32	33	34	35						
13											

I, Timothy L. Lapham, in a field survey on December, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
M-5: CLASON 1838, SET POST, HEMLOCK 12" S24-1/2W 31L., Y. PINE 12" N13-1/2W 49L.
HIGGINS 6/03/1977, SURVEY #77052 UNRECORDED, FOUND IRON & CAP, 3 WITNESSES
KING 10/30/1986, SURVEY 4-68, FOUND IRON AND CAP #12018, 4 WITNESSES
KING 9/9/1991, SURVEY 5-428, REVISION TO SURVEY 4-68, NO CHANGE IN CORNER

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
M-5: FOUND 1/2" IRON, 1 WITNESS OF 1977 SURVEY, AND 4 WITNESSES OF 1986 SURVEY, 3 WITNESSES CHECK PER RECORD BUT 4TH IS OFF, PROBABLE TRANSCRIPTION ERROR; CORNER POSITION MATCHES SWAMP CALL TO NORTH; CORNER POSITION MATCHES ROAD AND FENCE LOCATIONS ACCEPTED FOUND CORNER AS BEST AVAILABLE EVIDENCE OF ORIGINAL CORNER POSITION CORNER APPROVED AT PEER REVIEW MEETING HELD ON DECEMBER 21, 1994.
SEE REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.

APPROVED BY
PEER REVIEW
12-21-94
DATE P.A. 345 of 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
M-5: SET 5/8"x36" REBOD WITH 3-1/4" ALUMINUM REMON CAP
N48E 36.81 FOUND NAIL IN FENCE POST
S88E 27.13 FOUND NAIL IN FENCE CORNER POST
S27E 48.79 FOUND NAIL IN SOUTH GATE POST
S70W 35.59 FOUND NAIL IN CEDAR POST



Signed by Timothy L. Lapham Date 12/29/94
Surveyor's Michigan License No. 27595

SURVEY &
REMONUMENTATION

MAY 05 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
OGEMAW

(County)

Located In:

Corner Code #

- | | | | | | |
|---------------------------------------|---|------------|---|-----------|----------------------|
| 1. Public Land Survey, | T | <u>23N</u> | R | <u>4E</u> | <u>A-4</u> |
| | T | <u>23N</u> | R | <u>4E</u> | <u>A-5</u> ✓ |
| | T | <u>23N</u> | R | <u>4E</u> | <u>A-6</u> |
| | T | <u>23N</u> | R | <u>3E</u> | <u>M-4 AS 1/7/99</u> |
| 2. Property Controlling
In Section | S | <u>23N</u> | R | <u>3E</u> | <u>M-5 AS 1/7/99</u> |
| | S | <u>23N</u> | R | <u>3E</u> | <u>M-6 AS 1/7/99</u> |
| 3. Miscellaneous
Property in Sec. | S | T | R | | |
| | S | T | R | | |

LIBER

3 PAGE 02

STATE OF MICHIGAN
OGEMAW COUNTY
RECORDED

20 APR 95 10:19 A.M.

WANDA HUZIK
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	15		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

I, Timothy L. Lapham, in a field survey on December, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- A-4: COMMON CORNER WITH M-4, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994
- A-5: COMMON CORNER WITH M-5, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994
- A-6: COMMON CORNER WITH M-6, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- A-4: COMMON CORNER WITH M-4, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
- A-5: COMMON CORNER WITH M-5, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
- A-6: COMMON CORNER WITH M-6, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- A-4: COMMON CORNER WITH M-4, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
- A-5: COMMON CORNER WITH M-5, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
- A-6: COMMON CORNER WITH M-6, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.

Signed by [Signature]

Date 4/20/95

Surveyor's Michigan License No. 27595

