

**SURVEY &  
REMONUMENTATION**

Attach to: T23N R4E A-7 Seg. #1 MRD

MAY 03 1995

**COMMISSION LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

OGEMAW (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>23NR</u> <u>3E</u>	<u>M-7</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	<u>Seg. #1</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

LIBER 2 PAGE 266  
STATE OF MICHIGAN  
OGEMAW COUNTY  
RECORDED  
3 JAN 95 9:36 A.M.  
WANDA MIJIK  
REGISTER OF DEEDS  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K
2	6	5	4	3	2						
3											
4	7	8	9	10	11						
5											
6	16	17	18	15	14						
7											
8	19	20	21	22	23						
9											
10	30	29	28	27	26						
11											
12	31	32	33	34	35						
13											

I, Timothy L. Lapham, in a field survey on December, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:  
M-7: CLASON 1838, SET POST, LEANING HEMLOCK 20" S49W 14L.

LEANING HEMLOCK 18" N45W 51L.

KING SURVEY 4-65\*72, 10/30/1986, FD IRON, 4 WITS

KING LCRC 2-125, 12/02/1991, SAME AS 4-65\*72

KING SURVEY 5-128\*135, 9/09/1991, REVISION OF 4-65\*72 NO CORNER CHANGE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-7: FOUND 1/2" IRON IN CENTERLINE ROAD N-S AND ON N EDGE OF GRAVEL SURFACE EAST IN ACCORD WITH PREVIOUS SURVEYS AND LCRC, GLO STREAM CALL TO NORTH 0.5+/- CHAIN SHORT, BUT CORNER MATCH LOCAL FENCE AND APPEARS TO HAVE BEEN ACCEPTED BY RESIDENTS, ACCEPTED FOUND CORNER AS BEST AVAILABLE EVIDENCE OF CORRECT CORNER POSITION CORNER APPROVED BY PEER REVIEW MEETING HELD DECEMBER 21, 1994. SEE DOSSIER FOR ADDITIONAL INFORMATION

APPROVED BY  
PEER REVIEW  
12-21-94  
DATE P.A. 345 of 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


M-7: SET 5/8"x36" REROD WITH 3-1/4" AL. OGEMAW REMON CAP

N69E 51.41' FD NAIL IN POWER POLE

S53E 61.15' SET NAIL IN 20" WHITE PINE (PREVIOUS WITNESS APPEARS TO HAVE BEEN TO FACE BASE OF TREE)

S24W 89.80' SET NAIL IN 12" WHITE PINE

N39W 46.33' 1/2" CAPPED IRON #25852



Signed by Timothy L. Lapham

Date 12/29/94

Surveyor's Michigan License No. 27595

**SURVEY &  
REMONUMENTATION**

MAY 05 1997

COMMISSION

**LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
**OGEMAW**  
(County)

Located In: Corner Code #

- |                                       |              |                |                     |                          |
|---------------------------------------|--------------|----------------|---------------------|--------------------------|
| 1. Public Land Survey                 | T            | 23N            | 4E                  | <u>A-7</u> ✓             |
|                                       | T            | 23N            | 4E                  | A-8                      |
|                                       | T            | 23N            | 4E                  | A-9                      |
|                                       | <del>T</del> | <del>23N</del> | <del>R 3E</del>     | <del>M-7 AS 1/7/99</del> |
| 2. Property Controlling<br>in Section | S            | <del>T</del>   | <del>23N R 3E</del> | <del>M-8 AS 1/7/99</del> |
|                                       | S            | <del>T</del>   | <del>23N R 3E</del> | <del>M-9 AS 1/7/99</del> |
| 3. Miscellaneous<br>Property in Sec.  | S            | T              | R                   |                          |
|                                       | S            | T              | R                   |                          |

LICER 3 PAGE 03

STATE OF MICHIGAN  
OGEMAW COUNTY  
RECORDED

20 APR 95 10:20 A.M.

WANDA HUZIK  
Register of Deeds Stamp & File Number  
REGISTER OF DEEDS

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9	2												
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Timothy L. Lapham, in a field survey on December, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

- A. Description of original monument and accessories and/or subsequent restoration:  
**A-7: COMMON CORNER WITH M-7, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994**  
**A-8: COMMON CORNER WITH M-8, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994**  
**A-9: COMMON CORNER WITH M-9, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994**

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
**A-7: COMMON CORNER WITH M-7, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.**  
**A-8: COMMON CORNER WITH M-8, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIE FOR ADDITIONAL INFORMATION.**  
**A-9: COMMON CORNER WITH M-9, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIE FOR ADDITIONAL INFORMATION.**

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
**A-7: COMMON CORNER WITH M-7, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.**  
**A-8: COMMON CORNER WITH M-8, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIE FOR ADDITIONAL INFORMATION.**  
**A-9: COMMON CORNER WITH M-9, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIE FOR ADDITIONAL INFORMATION.**

Signed by [Signature]

Date 4-20-95

Surveyor's Michigan License No. 27595