

SURVEY & REMONUMENTATION

Attach to T23N R4E A-9 Sec. #1 MRD

MAY 03 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
OGEMAW
(County)

Located In: Corner Code ##

LIBER 2 PAGE 268
STATE OF MICHIGAN
OGEMAW COUNTY
RECORDED
3 JAN 95 9:38 A.M.

- | | | |
|------------------------------------|--------------------------|----------------|
| 1. Public Land Survey | T <u>23N</u> R <u>3E</u> | <u>M-9</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | <u>Sec. #1</u> |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

WANDA WUZIK
REGISTER OF DEEDS
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K
2	6	5	4	3	2					
3										
4	7	8	9	10	11					
5										
6	16	17	18	15	14					
7										
8	19	20	21	22	23					
9										
10	30	29	28	27	26					
11										
12	31	32	33	34	35					
13										

I, Timothy L. Lapham, in a field survey on December, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:


NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
M-9: CLASON 1838, SET POST, HEMLOCK 15" S40W 24L., HEMLOCK 12" N17W 23L.
HIGGINS SURVEY 2-467, 6-08-1978, FD IRON AND CAP, NO WITS
KING SURVEY 4-65*72, 10/30/1986, FD 1/2" IRON, 4 WITS
KING SURVEY 5-128*136, 9/09/1991, REVISION OF 4-65*72 (NO CORNER CHANGE)
KING LCRC 2-127, 9/09/1991, SAME AS 4-65*72
GRANGER SURVEY 5-385*6, FD 1/2" BAR AND CAP, 4 WITS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
M-9: NO EVIDENCE OF GLO CORNER FOUND, FOUND 1/2" CAPPED REROD MATCHING KING AND GRANGER WITNESSES
ACCEPTED FOUND CORNER AS BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER
CORNER APPROVED AT PEER REVIEW MEETING HELD ON DECEMBER 21, 1994
SEE DOSSIER FOR ADDITIONAL INFORMATION

APPROVED BY
PEER REVIEW
12-21-94 W
DATE P.A. 345 of 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
M-9: SET 5/8"x36" REROD WITH 3-1/4" ALUMINUM OGEMAW REMON CAP IN MON BOX
N44E 50.05' NAIL IN SE FACE OF POWER POLE
S62E 111.75' NAIL IN POWER POLE
S32W 52.99' NAIL IN POWER POLE
N44W 59.22' SE CORNER FOUNDATION
1.4' NORTH TO CENTERLINE OF EAST-WEST ROAD
0.3' EAST CENTERLINE OF PAVED ROAD SOUTH



Signed by *Timothy L. Lapham* Date 12/29/94
Surveyor's Michigan License No. 27595

**SURVEY &
REMONUMENTATION**

MAY 05 1997

COMMISSION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in
OGEMAW

(County)

Located In:

Corner Code #

- | | | | | | |
|---------------------------------------|---|------------|-------------|------------|------------------|
| 1. Public Land Survey | T | <u>23N</u> | <u>4E</u> | <u>A-7</u> | |
| | T | <u>23N</u> | <u>4E</u> | <u>A-8</u> | |
| | T | <u>23N</u> | <u>4E</u> | <u>A-9</u> | |
| | T | <u>23N</u> | <u>R 3E</u> | <u>M-7</u> | <u>AS 1/7/99</u> |
| 2. Property Controlling
In Section | S | <u>23N</u> | <u>R 3E</u> | <u>M-8</u> | <u>AS 1/7/99</u> |
| | S | <u>23N</u> | <u>R 3E</u> | <u>M-9</u> | <u>AS 1/7/99</u> |
| 3. Miscellaneous
Property in Sec. | S | T | R | | |
| | S | T | R | | |

LIBER

3 PAGE 03

STATE OF MICHIGAN
OGEMAW COUNTY
RECORDED

20 APR 95 10:20 A.M.

Register of Deeds, Stamp & File Number
WANDA HUZIK
REGISTER OF DEEDS

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Timothy L. Lapham, in a field survey on December, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- A-7: COMMON CORNER WITH M-7, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994
- A-8: COMMON CORNER WITH M-8, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994
- A-9: COMMON CORNER WITH M-9, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


- A-7: COMMON CORNER WITH M-7, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
- A-8: COMMON CORNER WITH M-8, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIE FOR ADDITIONAL INFORMATION.
- A-9: COMMON CORNER WITH M-9, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIE FOR ADDITIONAL INFORMATION.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- A-7: COMMON CORNER WITH M-7, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
- A-8: COMMON CORNER WITH M-8, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIE FOR ADDITIONAL INFORMATION.
- A-9: COMMON CORNER WITH M-9, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIE FOR ADDITIONAL INFORMATION.

	A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

Signed by



Date

4-20-95

Surveyor's Michigan License No.

27595