Ogemaw County Remonumentation

APR 08 1999

P

LAND CORNER RECORDATION CERTIFIC	CATE
Filing Requirement of Act 74 Mich BA	4070

For corners in	Filing Requirement of	Act 74, Mich. P.A	. 1970	SEC	TION
			1	LIBER $oldsymbol{3}$	PAGE 211
OgemawLocated in:	Corner Code #				STATE OF MICHIGAN
(County)					OGENAU COUNTY
1. Public Land Survey T2:	3N R <u>04E</u> K-11				RECORDED
T_	R			23	DEC 1998 3:48:26
<u>T</u>	R				B- 10420
2. Property Controlling S T	R			,	VANDA MUZIK
in Section S T				j	REGISTER OF DEEDS
3. Miscellaneous ST_	R				
Property in Sec. ST_	R				
			Regis	ter of Deeds S	itamp & File Numbe
4. Lot No, Recorded Plat					
5. Private Claims			А В	CDEF	6 4 1 7 2
			, [G H I J K
			2 - 6 -	- 5 4 -	
t,Timothy L Lapham, in a field surrequirements of P.A. 74, Michigan P.A. of 1970	rvey on _December_, 19 _9	8 do hereby state that	under 3		╂═╂═╂═┼═╁
conformance with regulations and rules therefore as	the comer points mention in	lines 1 and 2 above w	ere in 4 — 7—	- ė ė	10-11-1
United States Department of the Interior, Bureau of that the corner points mentioned in lines 3.4 and	Land Management or by a dec	ree of a Court of Law	of thes	- - - -	╎╸╎╸╎╸╎╸ ╎
Board of Land Surveyors or by a Decree of a	5 above were in conformance w	ith the rules of the Mic	chigan ⁶ 18	7-17-16-	15-14-11
recovered, found as expressed below:	Source, carr, established, 16	restablished, monum	ented, 7		
NOTE: Not more than 2 corners of the the			8 -19-	20-21-	22 23 24
NOTE: Not more than 2 corners, all in the s on this certificate	same town and range, may	be recorded	9	- - -	
			10 30		27-26-25
			11		
			12 -31-		34 35
A. Description of original monument and acce	ssories and/or subsequent r	estoration:	13		31 - 35 - 36
K-11: GLO 12/27/1844 J. Mullett set post	, , , , , , , , , , , , , , , , , , , ,				
Hemlock 14" S53E 20 lk		survey 4-177 7/1	19/1988 K Sh	ellenharger 1	Oll rose of an array
W. Pine 14" N18W 26 lk		witnesses as LCI	RC 1-348	ciiciinai 9ei 17	z rerod, same
section break 1970 N. Caldwell set iron	no witnesses	COUNTY road plans	2/1///1000 T		
distance to K-10= 2617.5 (1)		county road plans witnesses as LCF	RC 1-348	. Lapham sar	ne corner and
LCRC 1-348 7/19/1986 T. Lapham 1/2	' iron	SUDJOV Jungo oordo	.d 40404004	-	
N45E 46.68 10" R. Pine (2) S80E 35.71 6" R. Pine (3)		no witnesses	id 10/16/1991	I. Lapham c	orner not specified,
N40W 64.59 power pole (4)		distance to K-10=	2617.93 (6)		
N60W 90.91 4" birch (5)		section break 12	/22/4002 T L	and a second	
section break 1987 T. Lanham assures		section break 12 specified, no witn	esses	ipnam corner	material not
section break 1987 T. Lapham corner not distance to K-10≈ 2618.25	specified no witnesses	distance to K-10=	2617.93 (7)		
distance to K-9= 5236.50		distance to K-9≃	5235.85 (8)		
P. Bossitett					
B. Description of corner evidence found and/or K-11: No evidence of GLO corner or witnesses	method applied in restoring	or reestablishing co	orner:		
K-11: No evidence of GLO corner or witnesses. Found witness (2), measures 46.60. Four measures 90.80. All surveys appear to us	nd witness (3), measures 35	umate centerline of	roads north so	uth and west a	and trail east.
measures 90.80. All surveys appear to us best available evidence of the correct corr	se the same corner but it is	not tied back to the	GLO survey.	a 64.55. Foun Accepted the f	d Witness (5),
best available evidence of the correct corr	ner position.			isospiod (iio i	ound hon as the
C. Description of monument for corner and acce K-11: Set 5/8"x36" rerod with aluminum Ogeman	essories established to perp	etuate locating the	position of the	comer:	
Witnesses:	w county remon, cap				-/
N43E 46.60 spike in 10" red pine					101
S68E 35.74 spike in 6" red pine N35W 64.59 spike in power pole				1	
N65W 90.91 spike in 4" birch	Approved by	y Pee r Review			Malar Color
S45W 46.81 spike in fence post	11/15/67	7/4		E Pac	FESSIONS
	DATE	INITIALS			ANEYER :
		and the		· 10.	27595
1. /4/1	/				
Signed by		Date 12/	23/50	V.	ESSIGNA-
Surveyor's Michigan License No. 27595					
		•			