## SURVEY & REMONUMENTATION

MAY 0 3 1995

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	corners GOMMISS	ION ruing Require	ment of Act 74, Mich. P.A.			
<del></del>	OGEMAW (County)	Located In:	Corner Code ##		AGE 270 F NICHIGAN	
1	Public Land Survey	T _ 24NR _ 3E_	B-13	OGENA	4 COUNTY	
••	· abio cana barray	T R		Я <b>Е</b>	CORDED	
		T R T R		3 JAN 9	5 9:39 A.W.	
2.	Property Controlling	S T R		VAN	DA MUZIK	
3	in Section Miscellaneous	S T R S T R	<del></del>		ER OF DEEDS	
J.	Property in Sec.	S T R		Register of Deeds St	amp & File Number	
		Recorded Plat		A B C D E	FGHIJK	
5.	Private Claims				FGHIJK	
				2 6 + 5 - 1		
					<del></del>	
1. 2	imothy L. Lapham	, in a field survey onDecer	nber . 19 94		-9-10-11-1	
do	hereby certify that under re-	quirements of P.A. 74, Michigan P.A.	of 1970, the corner points mention	ned 6	<del></del>	
		n conformance with regulations an		the ''	-16-+-1514	
		uctions of the United States Depar a Court of Law and/or that the corne				
ab	ove were in conformance wi	ith the rules of the Michigan Board	of Land Surveyors or by a Decree of	of a	-21-1-22-23-1	
	urt of Law; established, a pressed below:	re-established, monumented, re-	nonumented, recovered, found	as 10 30 30		
		corners, all in the same town a	nd range may be recorded	11	28 - 27 - 26 -	
	on this certificate		id range, may be recorded	12 31 22		
				13		
A. Description of original monument and accessories and/or subsequent restoration: B-13: GLO CLASON, 1838, SET POST, HEMLOCK 16" N55E 31L., ELM 11" N40W 32L.;						
<b>D</b>		UG 1892, PLAT OF ROSE				
		AUG 1903, TRIM & MCGR			O WITS: HOOK	
		6, GREVE'S ADDITION TO				
		1, NO CORNER MAT, 1 WI				
		3, 1-368 JAN 1974, 1-4				
		Y 3-109 JULY 1974, FD			-	
	AS 1-98; LAPHAM SURVEY 5-108 JULY 1991, NO COR MAT, 1 WIT; LAPHAM SURVEYS 5-414 JAN 199 5-421 APRIL 1994, FD IRON, 1 WIT; LAPHAM SURVEYS 5-440 JULY 1994, 5-469 SEPT 1994, FD 5					
		CE LCRC 1-220	WELLINE BOKARIR 2-440 0	ODI 1994, 5-409 5	BP1 1394, FD 3	
8.	Description of corner	evidence found and/or method	applied in restoring or reesta	blishing corner:		
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: B-13: FOUND RECORDED WITNESS IRON IN MON BOX (ROAD PI), SET CORNER 3.0' NORTH ON NORTH-SOUTH						
	QUARTER LINE EXTENDED OF SECTION 6 T23N R3E					
	EXISTING POSITION LONG ACCEPTED AS COMMON CORNER FOR B-1 T23N R3E AND B-13 T24N R3E ACCEPTED MONUMENTED POSITION AS LONG ACCEPTED AND MOST HARMONIOUS POSITION FOR CORNER,					
	CORNER APPROVED AT PEER REVIEW MEETING HELD DECEMBER 21, 1994.					
	SEE DOSSIER F	OR ADDITIONAL INFORMAT	ion.			
				APPROVED B	<del>√</del> ]	
				PEER REVIEW	<i>i</i>	
				2/2/94 70	i	
				ATE P.A. 345 of 1	<del></del> [	
				// N.C. 1370 O.A.D O.A.1	<u></u>	
С	. Description of monum	ent for corner and accessories	established to perpetuate lor	cating the position of the	corner:	
Ŧ	C Description of monument for corner and accessories established to perpetuate locating the position of the corner. B-13: SET 5/8"x36" REROD WITH 3-1/2" ALUMINUM CAP MARKED 1994-27575 SOUTH 3.00 IRON BAR IN MONUMENT BOX					
		'X' IN CONCRETE, SE CO		ROSE CITY		
		CENTER OF CROSSWALK PO		<del></del>		
		SET NAIL IN POWER POLI			**************************************	
	S46W 51.84	CENTER OF CROSSWALK PO	OLE		the St. Land	
					reese y	

B SURYEYORK, M REVISED M AEVISEI