

**SURVEY &  
REMONUMENTATION**

JUL 28 1997

**COMMISSION**

**LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
OGEMAW  
(County)

Located In:

Corner Code #

- |                                       |   |             |           |               |
|---------------------------------------|---|-------------|-----------|---------------|
| 1. Public Land Survey                 | T | <u>24NR</u> | <u>3E</u> | <u>G-13</u> ✓ |
|                                       | T | <u>24NR</u> | <u>3E</u> | <u>H-13</u>   |
|                                       | T | <u>24NR</u> | <u>3E</u> | <u>I-13</u>   |
|                                       | T | _____       | R         | _____         |
| 2. Property Controlling<br>in Section | S | _____       | T         | R             |
|                                       | S | _____       | T         | R             |
| 3. Miscellaneous<br>Property in Sec.  | S | _____       | T         | R             |
|                                       | S | _____       | T         | R             |

LIBER

2 PAGE 274

STATE OF MICHIGAN  
OGEMAW COUNTY  
RECORDED

3 JAN 95 9:42 A.M.

WANDA MUZIK  
REGISTER OF DEEDS  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2			
3												
4	7		8		9		10		11			
5												
6	18		17		16		15		14			
7												
8	19		20		21		22		23			
9												
10	30		29		28		27		26			
11												
12	31		32		33		34		35			
13												

I, Timothy L. Lapham, in a field survey on December, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

G-13: COMMON CORNER WITH G-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DECEMBER 21, 1994

H-13: COMMON CORNER WITH H-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DECEMBER 21, 1994

I-13: COMMON CORNER WITH I-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DECEMBER 21, 1994

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-13:

H-13:

I-13:

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-13:

H-13:

I-13:



Signed by

*Timothy L. Lapham*

Date

12/22/94

Surveyor's Michigan License No. 27595

Attach to: T 24N R 3E G-13 Seg # 2 MR

SURVEY & REMONUMENTATION

MAY 03 1995

COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in OGEMAW (County)

Located In: Corner Code ##

- 1. Public Land Survey T 23NR 3E G-1
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R

LIBER 2 PAGE 256 STATE OF MICHIGAN OGEMAW COUNTY RECORDED 3 JAN 95 9:33 A.M. WANDA MUZIK REGISTER OF DEEDS Register of Deeds Stamp & File Number

- 4. Lot No. , Recorded Plat
5. Private Claims

Grid table with columns A-K and rows 1-13. Numbers 1-35 are placed in the grid cells.

Timothy L. Lapham in a field survey on December 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: G-1: GLO CLASON 1846, SET POST CEDAR 10" S60E 34 LKS FIR 4" S22W 31 LKS CADWELL SURVEY 1-540 DEC 1974, NO CORNER MAT, NO WITS KING LCRC 2-113 FEB 1991, FD IRON, 4 WITS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-1: FOUND 1/2" IRON FOUND RECORDED WITNESSES: N75E 131.97' SPIKE IN POWER POLE S02E 31.27' SPIKE IN POWER POLE ACCEPTED FOUND CORNER AS BEST AVAILABLE EVIDENCE OF THE ORIGINAL CORNER POSITION, CORNER APPROVED AT PEER REVIEW MEETING HELD DECEMBER 21, 1994 SEE DOSSIER FOR ADDITIONAL INFORMATION

APPROVED BY PEER REVIEW 12-21-94 DATE P.A. 345 of 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-1: SET 5/8"x36" ROD WITH 3-1/4" ALUMINUM OGEMAW REMON CAP IN MON BOX N76E 131.97 SPIKE IN POWER POLE S29E 84.38' SET SPIKE IN 8" SPRUCE S02E 31.27 SPIKE IN POWER POLE N26W 103.08' SET SPIKE IN 8" CEDAR

Signed by [Signature] Date 12/29/94 Surveyor's Michigan License No. 27595

**SURVEY &  
REMONUMENTATION**

**LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

MAY 03 1995

For corners in  
**OGEMAW**

**COMMISSION**

Located In:

Corner Code #

LIBER 3 PAGE 05

STATE OF MICHIGAN  
OGEMAW COUNTY  
RECORDED

20 APR 95 10:20 A.M.

WANDA NUZIK  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

- |                                    |   |     |   |    |               |
|------------------------------------|---|-----|---|----|---------------|
| 1. Public Land Survey              | T | 24N | R | 3E | <u>G-13</u> ✓ |
|                                    | T | 24N | R | 3E | H-13          |
|                                    | T | 24N | R | 3E | I-13          |
|                                    | T |     | R |    |               |
| 2. Property Controlling in Section | S |     | T | R  |               |
|                                    | S |     | T | R  |               |
| 3. Miscellaneous Property in Sec.  | S |     | T | R  |               |
|                                    | S |     | T | R  |               |

*Seg. #2 gm*

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Timothy L. Lapham, in a field survey on December, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

- G-13: COMMON CORNER WITH G-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994
- H-13: COMMON CORNER WITH H-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994
- I-13: COMMON CORNER WITH I-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DEC 21, 1994

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

- G-13: COMMON CORNER WITH G-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
- H-13: COMMON CORNER WITH H-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
- I-13: COMMON CORNER WITH I-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.

APPROVED BY  
PEER REVIEW  
*12-21-94* *JW*  
DATE P.A. 345 of 1990

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

- G-13: COMMON CORNER WITH G-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
- H-13: COMMON CORNER WITH H-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.
- I-13: COMMON CORNER WITH I-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION.

Signed by *[Signature]*

Date 4/20/95

Surveyor's Michigan License No. 27595