

**SURVEY &
REMONUMENTATION**

JUL 23 1997

COMMISSION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in
OGEMAW
(County)

Located In: Corner Code ##

1. Public Land Survey	T	<u>24NR</u>	<u>3E</u>	<u>G-13</u>
	T	<u>24NR</u>	<u>3E</u>	<u>H-13</u> ✓
	T	<u>24NR</u>	<u>3E</u>	<u>I-13</u>
	T	___	___	___
2. Property Controlling in Section	S	___	___	___
	S	___	___	___
3. Miscellaneous Property in Sec.	S	___	___	___
	S	___	___	___

LIBER 2 PAGE 274
STATE OF MICHIGAN
OGEMAW COUNTY
RECORDED
3 JAN 95 9:42 A.M.

WANDA MUZIK
REGISTER OF DEEDS
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2						
3											
4	7	8	9	10	11						
5											
6	18	17	16	15	14						
7											
8	19	20	21	22	23						
9											
10	30	29	28	27	26						
11											
12	31	32	33	34	35						
13											

I, Timothy L. Lapham, in a field survey on December, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.


A. Description of original monument and accessories and/or subsequent restoration:
G-13: COMMON CORNER WITH G-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DECEMBER 21, 1994

H-13: COMMON CORNER WITH H-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DECEMBER 21, 1994

I-13: COMMON CORNER WITH I-1, T23N, R3E, SEE LCRC FOR THAT CORNER AND REMONUMENTATION DOSSIER FOR ADDITIONAL INFORMATION. CORNER APPROVED AT PEER REVIEW MEETING HELD ON DECEMBER 21, 1994

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
G-13:
H-13:
I-13:

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
G-13:
H-13:
I-13:



Signed by [Signature]
Surveyor's Michigan License No. 27595

Date 12/29/94

**SURVEY &
REMONUMENTATION**

MAY 03 1995

LAND CORNER RECORDATION CERTIFICATE
COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
OGEMAW

(County)	Located In:	Corner Code #
1. Public Land Survey	T <u>23NR</u> <u>3E</u>	H-1
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	<i>Seg. #1</i>
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

LIBER

2 PAGE 257

STATE OF MICHIGAN
OGEMAW COUNTY
RECORDED

3 JAN 95 9:34 A.M.

WANDA MUZIK
REGISTER OF DEEDS
Register of Deeds Stamp & File Number

I, Timothy L. Lapham, in a field survey on December, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K
2	6		5		4		3		2		
3											
4	7		8		9		10		11		
5											
6	16		17		18		15		14		
7											
8	19		20		21		22		23		
9											
10	30		29		28		27		26		
11											
12	31		32		33		34		35		
13											

A. Description of original monument and accessories and/or subsequent restoration:

H-1: GLO CLASON 1846, SET POST
 SPRUCE 10" N22E 22LKS
 CEDAR 8" N18W 6LKS
 CALDWELL SURVEY 1-540 DEC 1974, NO CORNER MAT, NO WITS
 KING SURVEY 5-162 APRIL 1992, NO CORNER MAT NO WITS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-1: FOUND UNLEGIBLE CAPPED 1/2" IRON
 HISTORICALLY RECORDED AS A COMMON CORNER TO H13 T24N R3E
 THEORITICAL POSITION 1.24' WEST
 EXISTING CORNER WITHIN ALLOWABLE ERROR LIMITS FOR CORNER, ACCEPTED FOUND CORNER AS BEST AVAILABLE EVIDENCE OF THE CORRECT CORNER POSITION

CORNER APPROVED AT PEER REVIEW MEETING HELD December 21, 1994
 SEE DOSSIER FOR ADDITIONAL INFORMATION

APPROVED BY
 PEER REVIEW
 12-21-94
 DATE P.A. 345 of 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-1: SET 5/8"x36" ROD WITH 3-1/4" ALUMINUM OGEMAW REMON CAP IN MON BOX
 N23E 69.15' SET SPIKE IN 8" CEDAR
 S21E 88.04' SET SPIKE IN 8" SUGAR MAPLE
 S47W 87.40' SET SPIKE IN 8" SPRUCE
 N32W 74.74' SET SPIKE IN 6" ASPEN

Signed by [Signature]
 Surveyor's Michigan License No. 27595

Date 12/27/94