DEC 0 6 **1993** 

Surveyor's Michigan License No. \_

## COMMISSION LAND CORNER RECORDATION CERTIFICATE

Osceola	990
17N 7W A-1 Public Land Survey T R Description	990 nty
1. Public Land Survey T R	nty
TR	leng cour
TR	
I H	Kep
in Section S T R	
B. Miscellaneous S T R Register of Deeds Stamp	& File Number
Property in Sec. S T R	
. Lot No, Recorded Plat A.B.C.D.F.F.	
Private Claims	GHIJKLM
2 - 6 - 5 - 4 -	
3	
Matthew McClung November 7, 93 4 7 8 9-	10-11-12-
lo hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned	
1 lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land	15 14 13
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5	22 23 24
bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as	
xpressed below: 10302928	27 26 25
OTE: Not more than 4 corners, all in the same town and range, may be recorded	++++
on this certificate.	34 35 36
Description of original monument and accessories and/or subsequent restoration	
Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Orson Lyons on Oct	. 29,
1837. Set wood post 80.00 chains from the Southeast Corner of Sec Hemlock 10" N26E 151 lks.	etion 31.
Beech 10" N49W 41 lks.	
From 1891 to 1904 approximately, Osceola County had a remonumenta	ation
program, in which surveyors Temple and Trumbull, did the work. Fo	r the
most part, a 3" glazed tile filled with cinders from a forge, wer	e placed
at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back)	ed to be 3
design (continued of pack)	
Description of corner evidence found and/or method applied in restoring or reestablishing corner:	•
Found Tile, and 1/2" rod, also a 3/4" rod 18" below the road surf found a 5/8" iron and cap, No. 13037. Removed iron and cap and se	face. Also
County monument 6" below road surface. Corner is centered in road	t Osceola
intersection.	
OF MICA	77.25
Manual Ma	C.
MATTHEW	12 1
E A. McCLUNC	3 \
LAND	)
SURVEYOR NO.	18
ر 13037 مي المراكبي ا	. To the
	J. R. L.
Description of monument for corner and accessories established to perpetuate locating the position of the corner	******
Corner A-1. Osceola County Monument, which is a 3" brass cap moun	ted on a
1" pipe 18" in length. Corner fence post S40E 46.61 feet.	
Power Pole S18W 84.25 feet.	
36" W. Ash N25E 67.75 feet.	
Power Pole S52W 50.37 feet.	
12" N. Pine N65E 105.7 feet.	
gned by Methew M. Clary Date November 7, 1993	
urveyor's Michigan License No. 13037	

Liber A Page 10

OSCEOLA COUNTY REGISTER OF DEEDS

93 NOV 16 PM 2: 33

nancy Crawford

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County

This corner is recorded in miscellaneous notes of the Orient Township book with no definition of the corner. Witnesses 16" Ash NE 68'-7" Elm SW 48.8', dated April 1930.

The corner is again recorded in the Orient Township book, as NW Cor, Iron. Witnesses are 3" Norway Pine N72E 105.45 -30" W. Ash N20E 67.4 feet.

I used the Corner in the Paul Done survey, dated 25 April 1979, Recorded in Liber 366, page 487. I did not witness or described the corner.

Paul Lapham used the corner and recorded a PA. 74 certificate Aug. 14, 1979

117N, R7W Osceola Co