## SURVEY & REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

DEC 1 6 1996

Osceola Located In: Corner Code #    County	_	Filing Requi	rement of Act 74, Mich. P.A	A. 1970	202 2	C. Manage	
1. Public Land Survey  TINRTW TR	For corners in Osceola	Located In: Co.	mor Codo #		COMIN	NISSION	
TR.    Property Controlling   S   T   R	(County)	T <u>17NR7W</u>		Transfer Laboratoria	APPROVED	I AND COP	SA Itoma
2. Property Controlling S T R R R Register of Deeds Stamp & File Number Register of Deeds Stamp & File Numbe		TR			F.A. 34	5 UF 1990	INER
4. Lot No	in Section 3. Miscellaneous	S TR S TR		Book	Morek	eod Th	<u> </u>
I, Matthew McClung in a field survey onOT_20_19_96 to be reby state that under requirements of PA_74, Mcdigan PA_of 1970, the corner points mentioned in lines 1 and 2 above were in the corner points mentioned in lines 1 and 2 above were in the corner points mentioned in lines 1 and 2 above were in the corner points mentioned in lines 1 and 3 above were in conformance with cut does the Mcdigan PA_of 1970, the corner points mentioned in lines 1 and 3 above were in conformance with the use of the Mcdigan Board of Land Surveyors of y a Decree of a Court of Law, established, morumented. The corner points mentioned in lines 24 and 5 above wells in conformance with the use of the Mcdigan Board of Land Surveyors of y a Decree of a Court of Law, established, morumented. The corner law as extracted and the corner was extracted and the corner of th				Regi	Ster of Deeds S	stamp & File	Number
I. Matthew McClung in a field survey on	4. Lot No, Reco 5. Private Claims	rded Plat		A B	CDEF	G H I	J K L
L Matthew McClung is a field superon. OT-20.19. 95to between the testines of requirements of \$A.74 McKipun \$A.0 1970. The comer petite mentioned in fines. 1 and 3 above were in conformance with regulations and rules insertine are unusual or superintend the interior. Busers of Land Menagement of by a decree of Social flav and of that the corner points mentioned in lines 3.1 and 5 above were in conformance with regulations and rules insertine. Busers of Land Menagement of by a decree of Social flav and of that the corner points mentioned in lines 3.1 and 5 above were in conformance with the rules of the Michigan Beard of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented.  NOTE: Not more than 2 comers, at in the same town and range, may be recorded on this certificate.  NOTE: Not more than 2 comers, at in the same town and range, may be recorded on this certificate.  A Description of original monument and accessories and/or subsequent restoration:  The original corner was set by deputy surveyor Orson Lyons on 6 January 1846 Set wood post at 80.00 chains from South.  B. Ash 24" No56W 20 Lks.  Hemlock 16" S28W 15 Lks.  From 1891 to 1904 approximately, Osceola County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" glazed till effilled with cinders from a forge, were placed at each government set corner in the township. There were supposed to be 3 tills per corner, placed atop of each other, (continued on back)  B. Description of comer evidence found and/ornethod applied in restoring or receatablishing comer.  Found 1/2" re rod at surface, removed rod and excavated to 24". Found no other evidence of corner. Measured distance to C-5 to be 2, 841.82 feet.  Measured distance to A-7 to be 4734.91 feet. Roser states distance are 2841.47 feet and 4.733.92 feet. Roser states that he found Fluke iron. I moved the corner to fit Roser distances, as all are E.D.M. distance are 2841.47 feet and 4.733.92 feet. Roser states that he f				2 6-	5	3	2
on this certificate.  A Description of original monument and accessories and/or subsequent restoration.  The original corner was set by deputy surveyor Orson Lyons on 6 January 1848 Set wood post at 80.00 chains from South.  B. Ash 24" N38W 20 Lks. Hemlock 16" S28W 15 Lks. From 1891 to 1904 approximately, Osceola County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" glazed tile filled with cinders from a forge, were placed at each government set corner in the township. There were supposed to be 3 tile per corner, placed atop of each other, (continued on back)  B. Description of comer evidence found and/or method appled in restoring or reestablishing corner.  Found 1/2" re rod at surface, removed rod and excavated to 24". Found no other evidence of corner. Measured distance to C-6 to be 2,641.82 feet. Measured distance to A-7 to be 4734.91 feet. Roser states distance are 2641.47 feet and 4,733.92 feet. Roser states that he found Fluke iron. I moved the corner to fit Roser distances, as all are E.D.M. dictances. See Sketch of Fluke survey. Placed Osceola County Monument 2" below surface.  Corner C-7. Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 16" in length.  Telephone Pedestal N40W 50.25 feet. Power Pole S50E 61.98 feet. Power Pole (anchor) S35W 49.10 feet. Power Pole (anchor) S35W 89.10 feet. Power Pole S05E 61.98 feet. Power Pole S05E 61.98 feet. Power Pole S05E 61.98 feet. Power Pole S50E 61.98 feet.	requirements of P.A. 74, Michig conformance with regulations and United States Department of the that the corner points mentioned Board of Land Surveyors or by	an P.A. of 1970, the corner points m if rules therefore as required in the cur Interior, Bureau of Land Management I in lines 3, 4 and 5 above were in cor y a Decree of a Court of Law; est	entioned in lines 1 and 2 above we rent manual of survey instructions o t or by a decree of a Court of Law and oformance with the rules of the Mich	nder 4 7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7	17 16 20 21	15 -1	413-
A. Description of original monument and accessories and/or subsequent restoration:  The original corner was set by deputy surveyor Orson Lyons on 6 January 1848 Set wood post at 80.00 chains from South.  B. Ash 24" N36W 20 Lks.  Hemlock 16" S28W 15 Lks.  From 1891 to 1904 approximately, Osceola County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" glazed tile filled with cinders from a forge, were placed at each government set corner in the township. There were supposed to be 3 tile per corner, placed atop of each other, (continued on back)  B. Description of comer evidence found and/or method applied in restoring or reestablishing comer.  Found 1/2" re rod at surface, removed rod and excavated to 24". Found no other evidence of corner. Measured distance to C-6 to be 2,641.82 feet.  Measured distance to A-7 to be 4734.91 feet. Roser states distance are 2641.47 feet and 4,733.92 feet. Roser states that he found Fluke iron. I moved the corner to fit Roser distances, as all are E.D.M. distances. See Sketch of Fluke survey. Placed Osceola County Monument 2" below surface.  Corner is filled about 4 or 5 feet from original surface.  C. Description of monument for corner and accessories established to perpetuate locating the position of the comer.  Corner C-7. Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 18" in length.  Telephone Pedestal N40W 50.25 feet.  Power Pole Sour 61.98 feet.  Power Pole (anchor) S35W 49.10 feet.  Power Pole N30W 123.20 feet.		ners, all in the same town and rang	ge, may be recorded	10 30	29 -28-	27—2	6 25
A Description of original monument and accessories and/or subsequent restoration:  The original corner was set by deputy surveyor Orson Lyons on 6 January 1848 Set wood post at 80.00 chains from South.  B. Ash 24" N36W 20 Lks.  Hemlock 16" S28W 15 Lks.  From 1891 to 1904 approximately, Osceola County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" glazed tile filled with cinders from a forge, were placed at each government set corner in the township. There were supposed to be 3 tile per corner, placed atop of each other, (continued on back)  B. Description of comerevidence found and/or method applied in restoring or reestablishing corner.  Found 1/2" re rod at surface, removed rod and excavated to 24". Found no other evidence of corner. Measured distance to C-6 to be 2,641.82 feet.  Measured distance to A-7 to be 4734.91 feet. Roser states distance are 2641.47 feet and 4,733.92 feet. Roser states that he found Fluke iron. I moved the corner to fit Roser distances, as all are E.D.M. distances. See Sketch of Fluke survey. Placed Osceola County Monument 2" below surface.  Corner is filled about 4 or 5 feet from original surface.  Corner C-7. Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 18" in length.  Telephone Pedestal N40W 50.25 feet. Power Pole S50E 61.98 feet. Power Pole (anchor) S35W 49.10 feet. Power Pole N30W 123.20 feet.				]	32 -33	343	
other evidence of corner. Measured distance to C-6 to be 2,641.82 feet.  Measured distance to A-7 to be 4734.91 feet. Roser states distance are 2641.47 feet and 4,733.92 feet. Roser states that he found Fluke iron. I moved the corner to fit Roser distances, as all are E.D.M. distances. See Sketch of Fluke survey. Placed Osceola County Monument 2" below surface.  Corner is filled about 4 or 5 feet from original surface.  Corner C-7. Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 18" in length.  Telephone Pedestal N40W 50.25 feet.  Power Pole S50E 61.98 feet.  Power Pole (anchor) S35W 49.10 feet.  Power Pole N30W 123.20 feet.  Signed by Matheur Mallury.  Date September 20 1996 NO.	B. Ash 24" Hemlock 16" From 1891 to 190 program, in whice most part, a 3" at each governmentile per corner	N38W 20 Lks. S28W 15 Lks. O4 approximately, ch surveyors Templ glazed tile fille ent set corner in placed atop of e	Osceola County have early to the county have early to the township. The each other, (cont	did the word a for ere were cinued or	vork. For rge, were supposed	the placed	ໄ 3
Corner C-7. Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 18" in length.  Telephone Pedestal N40W 50.25 feet.  Power Pole S50E 61.98 feet.  Power Pole (anchor) S35W 49.10 feet.  Power Pole N30W 123.20 feet.  Signed by Mathemanian Date September 20, 1996 NO.	other evidence of Measured distance 2641.47 feet and moved the corner Sketch of Fluke	of corner. Measure be to A-7 to be 47 d 4,733.92 feet. R r to fit Roser dis survey. Placed O	d distance to C-6 34.91 feet. Rose oser states that stances, as all ar sceola County Mor	3 to be 2 er states he found re E.D.M. nument 2"	2,641.82 s distanc l Fluke i distanc	feet. e are ron. I es. See	
1" pipe 18" in length. Telephone Pedestal N40W 50.25 feet. Power Pole S50E 61.98 feet. Power Pole (anchor) S35W 49.10 feet. Power Pole N30W 123.20 feet.  MATTHEW A. McCLUNG LAND SURVEYOR Signed by Matthew Martines Date September 20, 21996 NO.	C. Description of monument	for corner and accessories estat	olished to perpetuate locating th	e position of the	e corner:		
Signed by Mathew Milliam Date September 20, 21996 NO.	1" pipe 18" in 1 Telephone I Power Pole Power Pole	length. Pedestal N40W 5 S50E 61.98 feet. (anchor) S35W 49.	0.25 feet. 10 feet.	' brass c	A SELECTION OF THE PERSON OF T	OF MIC	VAIC A
12027	Motho	Mille	_	. , <u>-</u>	R.	SURVEYO	$_{R}$ $\int_{\mathcal{S}}^{*}$
Winn 2,0 1 10 th 1 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		No	Date <u>S</u>	September	20 (199)	3 NO. 13037	Market By St.

96 NOV 26 PH 2: 15

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been entered in the County Surveyor records.

I have shown 2 L.C.R.C; Liber 1, Page 86; Liber 3, Page 94.

I have shown 5 PA 132; Liber 418, Page 37; Liber 335, Page 6599; Liber 346, Page 74; Liber 514, Page 327; Liber 299, Page 291.

Orient Township Records Book; Front Pages, Page 8 and Page 10.

SURVEY & REMONUMENTATION

DEC 1 6 1996

COMMISSION