## BURVEY & REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

OCT 2 9 1996

| For corners in  | ,  | COMMISSION   |
|---|--|--|
| Osceola Located In:   | Corner Code #  | APPROVED LAND CORNER<br>P.A. 345 OF 1990   |
|   | R <sub>8W</sub>  | Matthew McClery<br>26 Sept 1996  |
| 2. Property Controlling S T in Section S T 3. Miscellaneous S T Property in Sec. S T  | R  | Register of Deeds Stamp & File Number  |
| 4. Lot No, Recorded Plat  |  | ABCDEFGHIJKLM  |
| 5. Private Claims   |  | 1  |
| iMatthew McClung, in a field survey requirements of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and rules therefore as rec United States Department of the Interior, Bureau of Lar that the corner points mentioned in lines 3, 4 and 5 ab Board of Land Surveyors or by a Decree of a Courecovered, found as expressed below: | corner points mentioned in lines 1 and 2 above w<br>quired in the current manual of survey instructions<br>and Management or by a decree of a Court of Law a<br>sove were in conformance with the rules of the Mic | ere in of the 5  |
| NOTE: Not more than 2 comers, all in the same on this certificate.  | town and range, may be recorded  | 9<br>10 30 29 28 27 26 25<br>11<br>12 31 32 33 34 35 36  |
| The original corner was set 1847. Set wood post 40.30 Beech 12" N14E 10 lks Maple 12" S25W 27 lks From 1891 to 1904 approximation program, in which surveyor most part, a 3" glazed till at each government set contile per corner, placed at B. Description of corner evidence found and/or  | chains from East.  3.  3.  nately, Osceola County hers Temple and Trumbull, le filled with cinders to the township. The top of each other, (con  | nad a remonumentation<br>did the work. For the<br>From a forge, were placed<br>nere were supposed to be 3<br>ntinued on back)  |
| Found 5/8" X 24" long iron surface. Excavated to 28 Monument over center of the North and South   | " and found 3" clay tile   | e. Placed Osceola County   |
|   |  |  |
| C. Description of monument for corner and acc   | cessories established to perpetuate locating   | the position of the corner:  |
| Corner F-7. Osceola Count<br>1" pipe 18" in length.   | y Monument, which is a   | 3" brass cap mounted on a  |
| Power Pole S14W<br>5" Elm S08E 23<br>16" W. Pine S55<br>4" Elm N58W 45.   | .30 feet.<br>E 102.00 feet.  | A. McCLUNG LAND SURVEYOR   |
| Signed by Matthew MC  |  | August 13, 1996 (2)  |
| Surveyor's Michigan License No  | 13037  | The second state of the se |

OSCEOLA COUNTY REGISTER OF DEEDS

96 OCT 10 PM 4: 38 -

Mancy Crawford

SURVEY & REMONUMENTATION

OCT 2 9 1996

COMMISSION

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records.

Evart Township Survey records book; Front pages, page 3 and pages 30 and 31.