

FEB 1 6 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Filing Re	equirement of Act 74, Mich. P.	A. 1970	
Osceola	Located In:	Corner Code #		
(County) 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Property in Sec.	T_17IR_109 TR TR TR S TR S TR S TR S TR S TR	V <u>E-8</u>	I Amath	OVED LAND CORNER A. 345 OF 1990 Osceola County Oct 1998 of Deeds Stamp & File Number
4. Lot No, Recor	rdod Blat		****	
5. Private Claims	ded Flat		A B C	D E F G H I J K L
requirements of P.A. 74, Michiga conformance with regulations and United States Department of the I that the corner points mentioned	an P.A. of 1970, the corner point rules therefore as required in the Interior, Bureau of Land Manage in lines 3, 4 and 5 above were to a Decree of a Court of Law	12, 19, 98 do hereby state that on the mentioned in lines 1 and 2 above we are current manual of survey instructions ement or by a decree of a Court of Law are no conformance with the rules of the Mior, established, re-established, monument	ere in 5 of the 5 of the 6 of	-8 - 9 - 10 - 11 - 12 - 13 - 14 - 13 - 14 - 22 - 23 - 24 - 24 - 25 - 24 - 25 - 25 - 25 - 25
NOTE: Not more than 2 com on this certificate.	ners, all in the same town and	range, may be recorded	9 10 30 11 12 31	29 28 27 26 25- 32 33 34 35 36
1838. Set wood Beech 7" S3 Beech 7" N6 From 1891 to 19 program, in whi most part, a 3" at each governmentile per corner	orner was set by post 40.00 chars 31E 26 lks. 37W 11 lks 304 approximated the surveyors Telegraph for set corner corner atop of the placed atop of the set corner corner atop of the set corner atop of the set corner corner atop of the set corner corner atop of the set corner	y deputy surveyor J	had a remonded did the word from a forger here were sufficient on the latest the sufficient on the latest the	umentation rk. For the e, were placed upposed to be 3
Excavated to 6" below surface, stake, next to	' below surface removed pin. Ex position of ste se of pin, 6" be	and found 1 1/2" i kcavated to 18" bel eel pin. Placed Osc elow surface. Top o	ron pin. Exc ow surface a ecla County	and found wood Monument in
Corner E-8. Osc 1" pipe 18" in Cor. Steel Power S. er	ceola County Mon length. fence post N861 l post N52W 46.6	65 feet. 18E 107.95 feet. O. 66W 23.85 feet.	3" brass a	LAND
Signed by Malthall Surveyor's Michigan License N	M Cling	037 Date _	23 grov.	98

OSCEOLA COUNTY REGISTER OF DEEDS

98 NOV 23 AM 10: 38

Manay Crawford

SECTION

FEB 1 5 1999

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to

the tile. Notes of the work were kept in ledgers, and given to the

townships, and 1 of the townships have been recorded in the County Survey records. P.A. 74, Liber 2, page 48 by Hooth. 1 1/2" steel pin 0.2'below surface,

in fence lines E & W. Corner fence post East 29.67 Tele pole S15E 107.92 Fence Post N30E 76.20

by Wetherell. Fence post S89E 29.74' P. pole S14E 107.90 Page 132 6" Poplar S32W 45.00

P.A. 132, Liber 569, page 848, by Wetherell. Same Witnesses as Liber 374, pages 404 & 405.

Act. 132, Liber 367, page 645. Fence post East 29.67 Telephone pole S15E 107.92 Fence post S30E 76.20', (Note Hooth has N30E)

P.A. 132, Liber 374, pages 404& 405, P.A. 132, Liber 555, Page 740 & 741, by Wetherell. No witnesses.