## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| For corners in<br>0SCE0LA   |  |  |  |
|---|--|--|--|
| (County)  | Located in: C  | orner Code ##  |  |
| 1. Public Land Survey   | T R  | L-3  |  |
| 2. Property Controlling S   | 12 T R   | 3, 5, 6  |  |
| in Section S .  | T R  |  |  |
| 3. Miscellaneous S  |  | Regist   | er of Deeds Stamp & File Number                                    |
| Property in Sec. S  | TR   | <del></del>  |  |
| I. Lot No, Record   | led Plat   |  | A B C D E F G H I J K L M  |
| 5. Private Claims   |  |  | <u>רוויוויוייייי</u>   |
| CARL F. ROSER in a  | field survey onMARCH 24  | 3<br>4<br>19 _93 5   | 7  |
| do hereby certify that under requirem in lines 1 and 2 above were in conficurrent manual of survey instructions. Management or by a decree of a Court above were in conformance with the incourt of Law; established, re-established below; | ents of P.A. 74, Michigan P.A. of 1970,<br>ormance with regulations and rules<br>s of the United States Department of<br>t of Law and/or that the corner points<br>rules of the Michigan Board of Land S<br>blished, monumented, re-monume | the corner points mentioned Therefore as required in the The Interior, Bureau of Land mentioned in lines 3, 4 and 5 Surveyors or by a Decree of a Inted, recovered, found as                               | -19 - 20 - 21 - 22 - 23 - 24 - 25 - 25 - 25 - 25 - 25 - 25 - 25    |
| on this certificate.  |  | 12   | 313233343536-  |
| Description of principal manual   |  | 13   |  |
| i. Description of original monul<br>ذ-3   | ment and accessories and/or sul  | bsequent restoration:  | 6  |
| 3. Description of corner evidence L-3 REESTABLISHED N 1/4 COR SEC 12 MIDWAY & ON LINE BETNEEN FD NN & NE SEC CORS OF S-12. FOUND 1/2° REROD AS SET IN ERROR BY P.S. P.LAPHAM S87°57'32"N, 49.80'. COR                                       | ce found and/or method applied 3 ESTABLISHED SN COR DF N 1/2 OF NN 1/4 SEC 12 PER STANDARD BLM INSTRUCTIONS. E'LY EDGE OF MUSKEGON RIVER IS 326'± NEST.  | in restoring or reestablishing cor<br>5<br>ESTABLISHED SE COR OF N 1/2 OF<br>NW 1/4 SEC 12 PER STANDARD BLM<br>INSTRUCTIONS. CTR N-S TRAIL<br>IS 102' WEST. SMOOTH WIRE, ON<br>TREES, WEST IS 70' ± NORTH. | ESTABLISHED CTR OF NE 1/4 OF SEC 12 PER STANDARD BLM INSTRUCTIONS. |
| FALLS IN LOW, NET HARDWOODS.  | corner and accessories establis  | shed to perpetuate locating the p  | F. ROSER LAND SURVEYOR NO. 12028 LAND SURVEYOR NO. 12028           |
| L-3   | 3  | 5  | 6  |
| SET DNR MON & CEDAR POST.  3° MAPLE (CLP) N19°N 36.6'   | DROVE 1" x 72" SALV PIPE W/RLS<br>EAP. SET CED POST W/LOC TAG.   | DROVE 5/8" x 34" REROD W/RLS<br>CAP. SET CED POST W/LOC TAG.   | DROVE 5/8° X 34° REROD W/RLS<br>CAP. SET CED POST W/LOC TAG.       |
| 10" CEDAR 560°E 67.2"   | 2" N PINE N25"E 30.5"  | 12" R PINE N75°N 10.3'   | 2" BALSAM 585°E 69.9'  |
| 10" MAPLE \$15°E 32.5'  | 8° MAPLE N60°E 22.5'   | 7" R PINE N15"N 6.3"   | 4" ASH 545°E 17.7"   |
| 5" CEDAR S20°N 32.5"  | 2" W PINE S55"E 46.2"  | 5" W PINE 565°E 6.6"   | 6° ASH 525°E 17.6'   |
| FD 1/2" REROD W/<br>RLS CAP \$87°58'W 49.8'   | 5" ASH 560% 25.8'  | 7" W PINE \$40"W 8.8'  | 5° ASH S70°N 27.6'<br>FD 1/2° REROD W/<br>RLS CAP NB9°51'N 18.8'   |
| igned by Carl 7. K  | 101D 1.75-6  | >, <del></del>   |  |
| igned by  |  | Date   |  |
| iurveyor's Michigan License No.   | 12028  | FORM APPROVED I  | IY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1871           |

MAPPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYING, JAN. 25, 1971 REVISED MAY 14, 1975 REVISED JAN., 1963