

NOV 15 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Osceola
(County)

Located In: Corner Code ##

- | | | |
|---------------------------------------|-------------------------|-------|
| 1. Public Land Survey | T 18N R 7W | G-11 |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 4. Lot No. _____, Recorded Plat _____ | | |
| 5. Private Claims _____ | | |

APPROVED LAND CORNER
P.A. 345 OF 1990
Osceola County

Matthew A. McClung
October 11, 1994

Register of Deeds Stamp & File Number

I, Matthew McClung in a field survey on October 3, 191994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	13		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:
The original corner was set by deputy surveyor Orson Lyons on 14 April 1847. Set wood post 80.00 chains from South.
Beech 24" S27 1/4E 46 lks.
Beech 16" N77W 27 lks.

The corner has an LCRC Liber 2, page 206 by McClung
3 PA 132's Liber 418, Page 23, - 532,757

A. Continued on back.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
The corner is in a monument box 2 feet West of centerline of M-66. I have no description of the corner, as I could not enter the box.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Corner G-11 Monument box.

- Power Pole S60E 79.25 feet.
- Power pole N35E 174.25 feet.
- PK nail in cement filled 6" pipe fence post S75W 175.6 feet.
- Cement filled 6" pipe fence post S30 166.9 feet.

Signed by *Matthew A. McClung*
Surveyor's Michigan License No. 13037

Date October 3, 1994

OSCEOLA COUNTY
REGISTER OF DEEDS

94 NOV -4 PM 2:48

Nancy Crawford

557,251.

This Corner is recorded in the Township Book, page 52, Page 16 and front pages opposite index.

SURVEY &
REMONUMENTATION

NOV 15 1994

COMMISSION