DEC 0 6 1993 NOIBEN

	Committee	LAND CORN	ER RECORDATION CERTI	FICATE	
г-			rement of Act 74, Mich. P.		
FU	r corners in Osceola	Located In:	Corner Code ##		
1.	(County) Public Land Survey	T 18N 7W T R R	I-11	APPROVED LAND COR P.A. 345 OF 1990 Osceola County	VER Versy
	Property Controlling in Section Miscellaneous Property in Sec.	T R S T R S T R S T R		La NOV (1993 Register of Deeds Stamp &	File Number
		Recorded Plat			HIJKLM
5.		ung No		2 8 5 4 4 7 8 9	10 11 12
our Co ext ext	hereby certify that under relines 1 and 2 above were trent manual of survey instragement or by a decree of overwere in conformance vurt of Law; established, pressed below:	equirements of P.A. 74, Michigan P.A. in conformance with regulations as ructions of the United States Depart a Court of Law and/or that the convith the rules of the Michigan Board re-established, monumented, recorners, all in the same town a	of 1970, the corner points mention rules therefore as required in the rules therefore as required in the firment of the Interior, Bureau of Ler points mentioned in lines 3, 4 a of Land Surveyors or by a Decreemonumented, recovered, found	oned 6 18 17 16 16 18 17 16 16 18 17 16 16 18 17 16 18 17 16 18 19 19 19 19 19 19 19 19 19 19 19 19 19	22 23 24 27 26 25 34 35 36
A.	The original corner was set by deputy surveyor Orson Lyons on 6 Jan. 1848. Set wood post 80 chains from South. Beech 16" N84 1/4E 14 lks. Beech 10" N19 3/4W 13 lks.				
	78 lk. & Pin	e 38 1/2E 75 lk.,	gas pipe.	van Twp. Book as: P	ine N73E
В.	miscellaneou Description of corner Found a 3/4" I also found other 6" in 3/4" pipe an North 1/4 co distance of subdivision, the West One recorded dis concluded th County Monum	s pages as: Stone, evidence found and/or method pipe 30" long wit 2 stones near the diameter. I also find stones. From the rner of Section 34 2630.90 feet. the of section 34, by a Quarter Corner of tance of 2637.6 ft and stones ent, 8" below the	Telephone pole (applied in restoring or reesta h the top 6" bent bottom of the pi ound a 3" pipe 16 3" pipe , I meas , as 2627.50 comprecorded distance myself in 1964. section 35 as 26 in 1964 survey. to be the corner, road surface. The		d the rom the o the d ance to the es, I la ft.
C.	Corner I-11. 1" pipe 18"	Osceola County Moin length.	nument, which is	eating the position of the corner: a 3" brass cap moun	ted on a
	Telepho 4" Iron	DNR Sign Post S08 one pedestal N60W 4 pipe (pipeline ma Pole S18W 107.34 fe	6.25 feet. rker) N34W 54.85	MA MA	MICALG ITHEW CLUNG AND RVEYOR
Sig	ned by Mathe	w Millery	Date	November 8 2393	NO. 1037 10 11
Sui	veyor's Michigan Licen	se No130	37	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND	SORVEYORS, 1416 28. 1971
			LIBER A PAGE 37	*****	/// RENISED MAY 14, 1975 REVISED JAN., 1983

OSCEDLA COUNTY REGISTER OF DEEDS

93 DEC -1 AM 9: 43

Mancy Brawford

N39 1/2W 34.5 ft. & Fence post N48 1/2E 34.7 ft.

The corner is recorded in the Sylvan Twp. Book, by myself 23 June 1964 as: Iron and stone on old stone tele Pole N55-30W 38.25 ft. & Power pole S18W 31.9 ft.

A PA. 74 certificate dated 18 June 81, by myself.

A PA. 74 certificate by myself, dated 22 Feb. 89 along with a recorded survey in section 35.

B. The sketch below shows the angular relationship between the two corners, to the North One Quarter corner of Section 34.

N 1/4 Cor. Section 34

46° 18' 30" 8 6,46 FEET