SURVEY & REMONUMENTATION

SEP 1 5 1994

LAND CORNER RECORDATION CERTIFICATE

For corners in COV	MISSION Filing Require	ement of Act 74, Mich. P.	A. 1970	
Osceola (County)	Located In:	Corner Code ##	APPROVED LAT P.A. 345 0	F 1990
Public Land Survey	T <u>18N</u> R <u>8W</u> T R T R	E-5	Oscepla O Mattheway We green	Melen 1994
 Property Controlling in Section Miscellaneous Property in Sec. 			Register of Deeds	Stamp & File Number
4 Lot No.	Recorded Plat			
			2 6 5-	E F G H J K L N
do hereby certify that under rein lines 1 and 2 above were current manual of survey inst Management or by a decree o above were in conformance with Court of Law; established, expressed below:	equirements of P.A. 74, Michigan P.A. in conformance with regulations an tructions of the United States Depart of a Court of Law and/or that the corner with the rules of the Michigan Board or re-established, monumented, re-recorners, all in the same town and	of 1970, the corner points mentred rules therefore as required intended in the Interior, Bureau of the Interior, Bureau of the points mentioned in lines 3, 4 to fland Surveyors or by a Decremonumented, recovered, foun	oned 6 18 17- Land 7 20- and 5 8 19 20- e of a	21 22 23 24 28 27 26 25
on this certificate		id lange, may be recorded	123132_	33 34 35 36
The original 1847. Set wo Beech 18 Beech 20 From 1891 to program, in most part, at each gove tile per con	I monument and accessories and corner was set by cod post 80.00 chain 3" \$28E 40 lks. O" N32W 59 lks. O 1904 approximately which surveyors Tenda 3" glazed tile fiernment set corner rner, placed atop o evidence found and/or method a	deputy surveyor as from the South y, Osceola County mple and Trumbull lled with cinders in the township.	y had a remonum l, did the work s from a forge There were sup continued on be	mentation c. For the , were placed pposed to be 3 ack)
Found 1/2": 18" and fou Osceola Cou depth of 5"	rod at road surface nd tile encasing ro nty Monument over r below road surface	, bent to west , d. Broke 6" from od inside tile. . Corner is 5' e	then to south top of 1/2" re Drove rod and a ast of center1	monument to a ine. OF MICAGO MATTHEW A. McCLUNG LAND SURVEYOR NO. 13037
Corner E-5. 1" pipe 18" Teleph Power 40" Si	nent for corner and accessories of Osceola County More in length. In one pedestal N52E 3 Pole S30E 89.40 feet sar Maple S60W 60.2 Pole S85W 117.30 feet	nument, which is 32.88 feet. 20 feet.	ecating the position of th a 3" brass cap	e currer was
Signed by Matth	fow M Eleng	Date	June 12,	1994
Surveyor's Michigan Licer	nse No	037	FORM APPROVED BY MICHIGAN STAT	E BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197

LIBER A PAGE 153

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records.

This corner is shown in the front pages of the Osceola Township Book, as tile. Two witness are given.

REGISTER OF DEEDS

94 AUG 12 PH 3: 05

7 Janey Crawford