LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Osceola			Locate	d In		Corner C	ode#													
(County)																				
1. Public Land Survey		т	18N	R	8W	A9														
1. Public Land Survey		Ť	18N	R	9W															
2. Property Controlling		·				-														
in Section	S	. T		R																
	s	. Т		R		_														
3. Miscellaneous Property in Section	S	Т		R																
Property in Section	s ——	· T		R						Re	aist	ter of	f Dee	ds S	tamo	& Fil	e Nu	ımber		
	Ĭ <u></u> -	- '		• • •				L			9.0									
4. Lot No:	Recorde	d Pl	at:			<u> </u>		1 '	A E	3 C) E	F	G	н	J J	к	L M	ı	
5. Private Claims:								2	-6		5	$\left + \right $	- -	+	3	 2-	+			
I, <u>Craig W. McVean</u> , in a 1 requirements of PA 74, Mi and 2 above were in conforthe current manual of sur Interior, Bureau of Land Macorner points mentioned in of the Michigan Board o established, re-established	chigan PA c rmance with vey instruct anagement c lines 3, 4 ar f Land Sur , monument	of 19 n reg tions or by nd 5 veyo ed, re	70, the oulations of the a decre above version becovered	corne and Unite e of vere y a d, for	er points rules the ed States a Court o in confor Decree und as ex	mentioned in the preference of the preference of the preference of the preference of a Court of a C	n lines 1 quired in nt of the that the the rules of Law; ow:	3 4 5 6 7 8		8	8	7	16- 21-		15	11- 14- 23-		_13		
NOTE: Not more than		, all	in the	sam	e town	and range	, may	10	<u> </u>	Ò—	 _ 2	9	28- I	+-	27	26	十	_25		
be recorded on this ce	rtificate.							11	_	-	-	H	\dashv	+		\vdash	+	+		
								12	—3·	1	— 3:	¦—	33-	+	34	-35-		-36		
								13	L		L								ļ	
A. Description of origina	l monumer	nt an	ıd acce	ssor	ies and/	or subsequ	ent restoratior	1:												
2) Beech 9" N15°W 54 L. - 1847 – GLO – O. Lyon Corrected East from Standard post - From 1891 to 1904 approximately, Osceola County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" corne glazed tile filled with cinders from a forge were placed at each government set corner in the township. There was supposed to be 3 tile per corner, placed atop of each other, thereby making the corner 3 feet long.									Maple N20°W 40.7'; 4) 13″ Maple N15°E 18.2'; // Maple S62°W 24.2' - Rec. Survey L. 477, p. 104 – M. McClung – ences Corner.											
A9 & M9 – Standard Co	ornor Comi	mon	to Soc	10	& 30 T	18N R8W	and Sec 24 &	25 -	T181	N F	39V	V — F	-d h	ent	1∕₃" x	4" lc	ona i	iron r	od in on	
3" x 1' long cla iron rod. ½" ir best available	ny tile. Fd. on fits 2 Os	DNF stling	R Mon. g witnes	lying sses	g nearby s. Rema	/ pulled fror ins of fence	n ground. Duo esN,S&E. N	a dov	vn a	ind :	fou	nd b	olack	ccino	ders	unde	er til	e and	l around	
							· · · · · •													
C. Description of monu	ment for co	rner	and ac	ces	sories e	stablished	o perpetuate l	ocati	ng t	the (pos	itior	of	the c	orne	er:				
A9 & M9 – Replaced Be Top of tile set : \$58°W 24.55' N14°E 18.90' t N88°E 28.98' t N52°W 52.62'	2' below su to set Nail to set Nail a to set Nail a	irfac and and and	e. Add Tag in Tag in \ Tag in \	Rin Sou Nes Sout	g of Sto th side 1 t side Tr th side 4	ne around (11" Red Ma ri. 18" Red l !" Red Mapl	cap. Set Blue ple (#5) Maple (#4) e scribed 'XB ⁻	Cars Γ'	ioni	4' le te P	ong 'ost	j iroi : 1' N	n ret	par in	it.	CR/ Mc ROFE SUR	AIG VE/ E881	W. AN ONAL	E C	
Signed by:	rui	d	W.	/	Mu	Ven	Date:	10	/2	/z	00	07		A.	SA	•	9088		UF	
Surveyor's Michigan	License N	lo.:		390	88		<u>-</u> · · ·	` -/	1	, <u> </u>				- वि	A AN	OFE	3819	ONAL		