

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>19</u> N. <u>9</u> E. <u>W.</u>		G-11 H-11 H-13
2. PROPERTY CONTROLLING IN SECTION _____, T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 9-7 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

G-11

A. Temple 1892 found USBTs, set mon and marked: Pine stp 30 N34W 23.8'
Pine stp 18 N39E 21.1'

H-11

A Temple 1892 found USBTs, set tile mon and marked: Pine stp 17 N 9W 15
Pine stp 15 N 85E 21

H-13

A Temple 1892 Set mon and marked: 24" Pine stp N25W 47.0'
24" Pine stp S60W 4'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-11

Found Temple monument and remains of his witnesses.

H-11

Found Temple Monument and remains of his witnesses.

H-13

Found Temple MOnument and remains of his witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-11	H-11	H-13
Left 1/2" bar in 3" Vit tile in place. Added Cedar guard post.	Left 1/2" bar in 3" vit tile in place. Added Cedar guard post.	Left 1/2" bar in 3" vit tile in place. Added Cedar guard post.
B. Oak 16" N20W 19.1'	W. Oak 12" S 6W 20.4'	W. Oak 9" clump
W. Oak 22" S80W 39.6'	B. Oak 15" N72E 60.5'	of 3 N20E 61.0'
Maple 8" clmp S5E 57.9'	E-W Fence Due N 250'	Cherry 20" S28E 32.8'
N-S fence poor West 37'		
E-W Fence, Fair North 147'		

SIGNED BY *Kenneth J. Ostling* DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____