## SURVEY & REMONUMENTATION

SEP 1 0 1998

## SECTION

Surveyor's Michigan License No.

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1 Of Collicia III	•									
Osceola (County)	Located In:	Corner Code #		-						
1. Public Land Survey	TR_	T_19\R_10\W TR TR			APPROVED LAND CORNER P.A. 345 OF 1990					
Property Controlling in Section     Miscellaneous Property in Sec.	TR S TR S TR S TR		——————————————————————————————————————	Osceola County  28 May 1998  Marthan 911 Leng						
r reporty in 600.	·		<del>-</del>	Reg	ister of D	eeds S	tamp &	File Nu	ımber	
4. Lot No, Record	ded Plat			A B	СБ	E F	G H	IJ	K L I	
				2 - 6	<del></del>	4	- -	2-	<del> </del>  -	
I, <u>Matthew McClung</u> requirements of P.A. 74, Michigan conformance with regulations and United States Department of the Ir that the corner points mentioned is Board of Land Surveyors or by recovered, found as expressed believed.	n P.A. of 1970, the corner p rules therefore as required in hterior, Bureau of Land Mana in lines 3, 4 and 5 above wer a Decree of a Court of L	points mentioned in lines in the current manual of s agement or by a decree of the inconformance with the	3 1 and 2 above were in survey instructions of the of a Court of Law and /or	3 4 7 5 6 18 7 8 19		9	1015	11	13-24-	
NOTE: Not more than 2 come on this certificate.	ers, all in the same town a	nd range, may be reco	orded	9	29_	28	27	—2 <del>6</del> —	25—	
				11 12 31	32_	33	34	35	36—	
A. Description of original more The original cor 1938. Set 12" Be	rner was set b	y deputy su	rveyor Sylve	ester outh.	Sible	y Ju	ly 7	<u></u> ,	<b>I</b>	
From 1891 to 190 program in which part, a 3" glaze each government tile per corner,	n surveyors Te ed tile filled set corner in	emple and Tr I with cinde I the townsh	rumbell did t rs from a fo ip. There w	the wo orge, vere s	rk. were uppos	For a place ed to	most ed at	3		
B. Description of corner evide	ence found and/or metho	od applied in restoring	or reestablishing cor	nar-						
Found 1/2" Iron x 2: 14' rock. tile. Placed Os surface. Corner centerline of Ea	Pipe 5" below Excavated to sceola County is 2.0 East	road surfa 24" found Monument in of centerl	ce. Excavat 1/2" rod. in center of t	ed to Sout	heast '' bel	cori	ner o	of		
C. Description of monument fo	or corner and accessorie	s established to perpo	etuate locating the nos	sition of the	o corner					
Corner I-7. Osce 1" pipe 18" in 1	ola County Mo					ounte	ed on	ı a		
Brace Fence	Post S70E	62.25 feet.			.d	PASSES IN	F MI			
	W 46.0 feet. W 52.75 feet S70W 78.4 fe				87.8		TTHEV			
					ecolor.		LAND RVEYO	R	F. See	

SURVEY & REMONUMENTATION

SEP 1 0 1998

SECTION

OSCEOLA COUNTY REGISTER OF DEEDS

98 JUL 23 PH 12: 40

Maney Crawford

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been entered in the County Surveyors records.

LeRoy Twp. Book, page 2(fr pages) Tile and Rod Elm NE 47 feet Maple SE 128.5 feet.

Act. 132 Liber 374, page 487, by Erickson S50W 51.5 feet 6" Pine S35W 52.0 feet 6" Pine S45E 39.0 feet Str Post

Liber 492, Page 111 & 112 by Ray Fd. 5/8" iron bar S75E P.P. 82.64 feet S50W 6" Red Pine 46.70 N40W 8" Maple 51.92 feet N40E DBL 8" Maple 51.92 feet

Act 74
Liber 2, page 166, by Erickson
Fd iron in Bit Intersection
S50W 51.5 feet 6" R. Pine
S35W 57.0 feet 6" R. Pine
S54E 39.0 feet Str Post
Centerline Rd. N&S
Centerline RD E&W

Liber 2, Page 111, by Hooth Fnd 1/2" pipe, buried 12", 2 1/2 E. of Centerline N-S Rd. & 2 S. of Rd. E. & on S. Side of trail W.

N20E 65.64 feet 14" Twn Ash N40E 45.95 feet 4" Ash S40W 57.11 feet 4" R. Pine N25W 51.93 feet 3" Ash