AUG 2 8 1999 LAND CORNER RECORDATION CERTIFICATE

For corners in	COMMISSITIME	Requirement of	Act 74, Mich. P.A.	. 1970
Osceola	Located In:	Corn	er Code ##	
(County)				
1. Public Land Survey	19N T R T R		I-11	APPROVED LAND CORNER P.A. 345 OF 1990
	T R T R		·	Osceola County 29 June 1993
2. Property Controlling	S T R			mouther Millens
in Section	S T R			
3. Miscellaneous	S T R			Register of Deeds Stamp & File Number
Property in Sec.	S T R			
4. Lot No,				A B C D E F G H I J K L I
5. Private Claims				2 6 5 1
•				3
Matthew Modland	•	12 June	1995	4 7 8 9 10 11 12
Matthew McClung	, in a field survey on $_$, 19	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3. 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				
NOTE: Not more than 4 on this certificate	•	town and range, i	may be recorded	11
A Description of original	l monument and access	ories and/or subse	equent restoration:	13
28, 1856. Set we Hemlock 12' Hemlock 12' From 1891 to 19 program, in white most part, a 3' at each governmentile per corner B. Description of corner Found 2" pipe 2	orner was set k rood post 40.00 N66W 27 Lks. S45E 28 lks. 804 approximate tch surveyors 1 glazed tile in ment set corner r, placed atop evidence found and/or 2" below surfaced tile 34" below	oy deputy so chains from the and 's in the too of each other method applied in the too of surface.	arveyor France the West. a County had Irumbull, dicinders frownship. There is the continuous of the c	cis Coleman on Sept. (Reestablished Cor) a remonumentation d the work. For the m a forge, were placed e were supposed to be 3 nued on back)
C. Description of monum	ent for corner and acce	ssories establishe	d to perpetuate loca	ting the position of the corner:
Corner I-11. is on a 1" pipe 1 6" Channe Power Pol Telephone 14" Sugar	s Osceola Coun 8" in length. 1 Iron Gate Po e N82E 32.4 fe Pedestal N40W Maple S08W 14	ty Monument st N10E 194 et O.B.P. 42.31 feet 4.95 feet.	, which is a .7 feet.	3" brass cap mounted .s now a stump.
ON 2 + 44	Ann Marollo) }		ne 19 1995
Signed by	un mille	ny	Date	
Surveyor's Michigan Licen	se No1	3 637)AM APPROVED BY MICHIGAN STATE BORRD OF LAND SURVEYORS, JAM. 28, 197 REVISED MAY 14, 197

OSCEOLA COUNTY REGISTER OF DEEDS

95 JUL -6 AM 10: 40

nancy Crawford

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records

I have shown 1 PA. 132 certificates using this corner.

I have shown 2 LCRC Certificates Act 74.

County Survey Record, Middle Branch Township Book, Pages 24 and 25.