## SURVEY & REMONUMENTATION

SEP 1 0 1998

## LAND CORNER RECORDATION CERTIFICATE

	Filing	Requirement of Act 74, Mich. P.A	SECTION
For corners in			,
Osceola	Located In:	Corner Code #	
(County)			APPROVED LAND CORNER
1. Public Land Survey	T19N7		P.A. 345 OF 1990
tit dame but	TR_ T R_		Oscepta County
	TR_		Mathew M Ching
2. Property Controlling	S TR_		28 may 1998
in Section	s TR_		
3. Miscellaneous	s T R		Register of Deeds Stamp & File Number
Property in Sec.	·		
<b></b>	rdad Diat	·	ABCDEFGHIJKLM
4. Lot No, Reco	rded Flat		1 2 1 1
5. Private Claims			2 6 5 7 1
		<b>-</b>	3 10 11 12
Matthew McClur	ng in a field survey on	5-25 , 19 $98$ do hereby state that her points mentioned in lines 1 and 2 above w	under 4 vere in 5
requirements of P.A. 74. MIVIN	4017 1 21 11 11 11	IL	
and the Department of the	illifetiol. Dinead of Earlie	"	Cnidaii _
that the corner points mentions	ed in lines 3, 4 and 5 above by a Decree of a Court	e were in conformance with the rules of the inter- of Law; established, re-established, monum	nented, 8 19 20 21 22 23 24
recovered, found as expressed	Delost,		
NOTE: Not more than 2 or	omers, all in the same to	wn and range, may be recorded	10 30 29 28 27 26 25
on this certificate.			11
,			12 31 32 33 34 35 36
			13
tion of original I	monument and access	ories and/or subsequent restoration: oty surveyor Frances Co	oleman on Oct. 29, 1856.
The corner was	s set by depu	ety surveyor Frances of	oleman on Oct. 29, 1856. (resurvey)
Set Quarter se	ection post 3	39.80 chains from East	•
Spruce	Pine o Roc	W 124 lks.	
			had a remonumentation , did the work. For the
program, in W	hich surveyo	rs Temple and Trumbull	, did the work. For the from a forge, were placed
most part, a	3" glazed ti.	rner in the township.	from a forge, were placed There were supposed to be 3 continued on back)
at each gover	nnent soo oo	top of each other, (c	continued on back,
tile per corn	evidence found and/o	r method applied in restoring or reestable	shing corner:
B. Description of corner	Couth	28 8 feet from C/L in	East and West Road and East t 6" below surface.
Found monumen	t box bounn h 21 A feet.	28.8 feet from C/L in Found State Monument	
of Drive Sout	M 21.0 1		28 . C. 37 777 2
			NATTUCKI W
	,		(A) WALLIE
			A. MCLLUNG LAND SURVEYOR NO.
			16 1002 /61
o Description of month	ment for corner and ac	cessories established to perpetuate local	ting the position of the corner
C. Description of mone.		t in monument box.	LAND LAND
		ument in monument box.	surveyor surveyor ting the position of the corner 13037
Power P	ole S52W 102	.9 feet. O.B.P.	16 3 feet. O.B.P.
	. C+b c1/10	road, Eddo C	
R/W Mar	ker North	Road West end S60W	42.5 feet.
Culvert	Cap 18223 MH	II NO3W 103.59 feet.	·
Trong			
	, ,	$\sim$	12 T 1. 1005
Signed by Man	Thous M	(Xurge	Date 23 July 1998
Signed by	Alkary Har	130/37	•
Surveyor's Michigan Li	Ceuze MO		·

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been entered in the County surveyors records.

MDSH&T Corner card.
Found 2 1/2" tile placed 1/2" rod inside tile.
15" Oak S38W 101.76'
9" Oak S05W 58.23'
8" Oak S40E 86.83'

Act. 74. Liber 1, page 356, by McClung Found Monument box in S. shoulder of M-61 15" Oak S38W 101.76" 9" Oak S05E 58.23' 8" Oak S40E 86.83"

Act 74
Liber 2 Page 157 by Fluharty
Fd Iron in Monument Box
28.8° S of C/L of M-61
Iron in Monument box
E End 15" culv. S22W 16.4°
R/W Marker S03W 46.54°
10" Oak S47E 84.23°
7" Cherry S32W 83.95°

Act 132 by Fluharty
Liber 621 page 883 and 884
FD Iron in Monument Box
E. End 15" Culv. S22W 16.4 '
10" Oak S47E 84.83'
4-7" Cherry S32W 83.95'

Act 132 Liber 363 Pages 174, 175 and 176 by Fluharty Fd. Iron in Monument Box Witnesses the same as Liber 621 pages 883 & 884 REGISTER OF DEEDS

98 JUL 23 PM 12: 41

SURVEY & REMONUMENTATION

SEP 1 0 1998

SECTION