SURVEY & REMONUMENTATION

NOV 0 2 1998

SECTION		D CORNER RE					•		<	eg.
For corners in				Rسرا	ereço	ded :	to co	rreo	t	υ
Osceola Located In: Corner Code #						3, Pa			- ,	
(County)				C	orded	23 J	уту т	998.		
1. Public Land Survey	<u>T 19</u> NR		M-5							
TR					APPROVED LAND CORNER P.A. 345 OF 1990					
	T R	<u> </u>	q·#2				ceola Co			
2. Property Controlling	S TR S TR		<i>(</i>)		9/	MOU	W III	79/	wy	
in Section 3. Miscellaneous			28 M	y 19	98					
Property in Sec.	S TR				Regis	ster of De	eds Star	mp & F	ile Nur	nber
				<u>L</u>	, , , , , , , , , , , , , , , , , , ,					
4. Lot No, Record 5. Private Claims	led Plat		·- <u>-</u>	<u> </u>	A B	CDI	FG	и т	лк	L
5. Private Claims					1	ŤŤ		ŢŤ	ŢÏ	Ţ
					3 3	5	1			
, Matthew McClung	∄in a field survevon.	5-25 .19	98 do hereby	state that under	4 7-			_10	_11	12_
requirements of P.A. 74, Michigan	n P.A. of 1970, the com	ner points mentione	d in lines 1 and :	2 above were in	5			_ _	-	\perp
conformance with regulations and United States Department of the Ir	nterior, Bureau of Land I	Management or by a	decree of a Cou	rt of Law and /or	6 -19	17_	16	-15	-14-	 1,3
that the corner points mentioned it Board of Land Surveyors or by					7	-		+		
recovered, found as expressed bel	ow:				8 19	20_	21	_2'2	-2 ¹ 3	—2'4—
NOTE: Not more than 2 com	ers, all in the same tov	wn and range, may	y be recorded		9	1		+++		-
on this certificate.					10 30	- 29 	28	-27-	-26 	25-
					12 31-	32	33	34	35	36-
					13		Ĭ	Ĭ	لــــّـــ	
	.00 chains for S31W 43 Lks N57W 74 lks O4 approximate Ch surveyors glazed tile ent set corr	from the S xs. ately, Osc Temple a filled w her in the	south. eola Cou and Trumk vith cinc e townshi	unty had oull, did ders from ip. There	a remo the t a for were	(resonument or the contract of	rvey ntati For were	on the place	ed	
B. Description of corner evid										
Found Monument E	Box in C/L c	of M-61.	Found St	tate Monu	ment.		OF	MICA	Sec. Sec.	
						A P	Section & Sales	Manhaman and		À
				•		19/	MATI		~\\	The state of
							A, Mc۲	ND TOM	3].	* }
						RE.	SURV	EYOR] 5	¥
							N 136	10. 177		1
	•	,						444 4 4 4 4 A 4 4 A 4 A 4 A 4 A 4 A 4 A	Oly 1	*
C. Danadaskan afarananak	fan d	والمالم ومارية		. In a stime that may	-14:		MED L	ANU	AND SERVICE	
C. Description of monument			a to perpetuate	riocaung the pos	SIUON OI III	e comer.				
Corner M-5 is a	MDSH&T monu	ment.			-		121 25 1 1 1			
	North 50.35					v	,	**		
	f Culvert S1 f Culvert S2									
	6 Culvert 52 6" N50E 175.		.550.				~			
- -										
					•	-				
no al	Mar 20			g		<u>. </u>				
Signed by	III Olen	<i>y</i> 23037		Date 15	<u>0 CT</u>	1	8			
Surveyor's Michigan License I	Vo	/1303 <i>l</i>			2	. ; '			-	

OSCEOLA COUNTY REGISTER OF DEEDS

98 OCT 23 PM 12: 05

Mancy Crawford

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been entered in the County surveyors records.

MDSH&T Corner card. Found Axle Shaft beside old (decayed wood stake. 13" J. Pine S45W 79.95' 10" J. Pine S40E 59.82' 8" J. Pine North 54.93'

Service 11 Military 11

> Act. 74. Liber 1, page 356, by McClung Fd. Mon. box in M-61 Mon. box in M-61

Act 74 Liber 2 Page 157 by Fluharty Fd 5/8" w/metal cap 5/8" with metal cap

4.78

SURVEY & REMONUMENTATION

· 1945年 1946年

NOV 0 2 1998

SECTION

Bagaga Barrigas

90 5 5 5 5 5 7 F

3 Kar 2 () 1 86