SURVEY & REMONUMENTATION

AUG 27 1996

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P.A. 1970

COMMISSION

For corners in	Filing Requi	irement of Act 74, Mich. P.A	A. 1970
Osceola		_	
(County)	Located In:	Corner Code ##	
	19N 7W	M-12	APPROVED LAND CORNER
 Public Land Survèy 	T R		P.A. 345 OF 1990
	T R		Osceola County
	T R		Mathew My Kung
	T R		250 ales 1991.
2. Property Controlling	S T R		
in Section	S T R	***	
3. Miscellaneous	S T R	i	Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4 4 3 4 4 5	anadad Net		
	ecorded Plat		A B C D E F G H I J K L M
5. Private Claims			2 5 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
			3 1 1 1 1 1 1 1
Matthews McClass	0.9	T 1 100	
Matthew McClung	in a field survey on	July 199	
do hereby certify that under req	uirements of P.A. 74, Michigan P.	A. of 1970, the corner points mention	ned
	-	and rules therefore as required in	the 6 18 -17 -16 -15 -14 -13 -1
-		artment of the Interior, Bureau of L	
		ner points mentioned in lines 3, 4 an I of Land Surveyors or by a Decree	*1-19-1-21-21-21-22-1-23-4-24-1
		-monumented, recovered, found	
expressed below:	, databalles, monamentos, re	monamented, resovered, round	10 30 29 28 27 26 25
NOTE: Not more than 4 co	orners, all in the same town	and range may be recorded	
on this certificate.		and range, may be recorded	12 31 32 3 34 35 36
			13
A. Description of original n	nonument and accessories a	nd/or subsequent restoration:	
•			eman on October 29, 1856.
	0.00 chains from		man on october 20, 1000.
	S50W 24 Lks	one boutin.	
	N34W 41 Lks		
		Occasia County ha	d a namanimantation
			d a remonumentation
			lid the work. For the
			om a forge, were placed
			re were supposed to be 3
tile per corner	, placed atop of	each other, (cont	inued on back)
B. Description of corner ev	vidence found and/or method	applied in restoring or reestab	olishing corner:
Found Occopin C	aunti Manumant au	on conton of tile	at anound ounfros
			at ground surface.
preer hence bos	t accompanies cor	ner.	
,	•		
			all and a second
C. Description of monumer	it for corner and accessories	established to perpetuate loca	ating the position of the corner:
Corner M-12 is	Osceola County M	onument, which is	a 3" brassecap mounted
on a 1" pipe 18		Oliometro, witter in	d o brabbacap moneped
24" R Oak		O.B.T.	
6" Spruce	S80E 18.11 fe		A Comment of the second of the
18" R Oak	N6W 10.40 fee		A MACLUNG
2" W. Pine	N8E 28.6 feet.		LAND
			E SURVEYOR /S
			A MCCLUNG LAFID SURVEYOR 13037
, ,			THE PARTY OF THE P
An all	' Mrcall	т	Tr. 8 1006
Signed by	W The Keny	Date	13037 (1y 8, 1996
, ,_,	No 13037		
Surveyor's Michigan License	100		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYDRS, JAN. 28, 1971 REVISED MAY 14, 1975
			REVISED JAN., 1983

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records.

Middle Branch Township Record Book Pages 10 and 11. The call 23" R. Oak S50E 3.0f feet was used to locate the corner.

There is 1 LCRC; Liber 3, page 96

There are 3 PA 132 surveys; Liber 580, Page 72; Liber 326, Page 178; Liber 519, Page 658.

Muskegon Bank Subdivision.

REGISTER OF DEEDS