LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 19 N. S., R. 8 E. W.	D-10
2. PROPERTY CONTROLLING IN SECTION 29	,T. 19 N. S., R. 8 E. W.	4, 5, 8
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 7-16, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C (cont.)

8
Set 1 1/4" x 6' pipe welded on top
of 7' steel fn post in 9' muck & wat.
Set 5/8" x 34" re-rod & ced post w/loc. tag. N88°53'E 235.0'
Set 5/8" x 34" re-rod & ced post w/loc. tag. N3°29'W 75.0'
Edge Lake Due E 196'±6'
Edge Lake Due N 35'±6'
Edge Lake Due W 37'±6'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

4 Established center of NW1/4 of Sec. 29 per std. B.L.M. instructions for subdividing sec. Corner is on our brushed-out true line to E & S.
5 Estab. N1/8 cor on N-S1/4 line of Sec. 29 per std. B.L.M. instr. for subdividing sections. Corner is on our brushed-out true line to S & W.
8 Estab. W1/8 cor. on E-W1/4 line per std. B.L.M. instr. Cor. falls in Big Long Lake (set pipe) and is on our brushed-out tree line to N & E.
D-10 Estab. ctr. of Sec. 29 at intersection of one-quarter lines. Cor. is on our brushed-out true line to N & W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4	5	D-10
Set 5/8" x 34" re-rod w/RLS cap & ced post w/loc. tag	Set 5/8" x 34" re-rod w/RLS cap & ced post w/loc. tag.	Set 5/8" x 34" re-rod w/RLS cap & ced post w/loc. tag
7" Maple N50°E 23.9'	6" Maple N85°W 18.1'	Power Pole N30°E 68.2'
6" Sug Map S80°W 28.7'	3" Beech N85°E 13.0'	4" Maple N75°E 31.2'
Fd. 3/4" iron rod w/RLS cap S3°39'E 3.77'	5" Sug Map S30°W 13.2'	3" Maple S70°W 16.9'
	Fd. 3/4" iron rod w/RLS cap S3°54'E 7.79'	W end of steel gate S05°E 16'

SIGNED BY Carl F. Roser DATE 7-17-80

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Hartwick Township
Osceola County

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET