LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 19 N., R. 8 W.	C-9, D-9, E-9
2. PROPERTY CONTROLLING IN SECTION 29	T. 19 N., R. 8 W.	2
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 16, 19 80, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C (cont.)

E-9
Fd. brass cap mon. & 1 tile;
added ced post w/loc. tag.
Power Pole N25°E 16.7'
7" Ash S45°E 30.0'
9" Maple S30°W 55.0'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-9 Fd. Brass capped monu. & 1-3" tile that fits 1 McClung wit. Cor. is on boun. of plat.

C-9 Recovered and accepted Brass-capped Osceola County Monument and old 3" tiles; corner fits two McClung wits.

D-9 Found 3 - 3" tiles w/cinders and 5/8" x 20" iron lying on ground. Brass cap monument was gone. Replaced tile with Dept. monument. Corner fits 3 - McClung Wits.

2 Establish. E. 1/8 Cor. on N. line S-29 midway & on line between NE ¼ N½ cor. of S-29.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-9
Fd. brass cap mon. & 3/4" pipe in 3" tile;add ced post w/loc tag.
6" Ash N50°W 59.77
8" Ash S10°E 26.44
6" Mapl S50°W 54.10
Ctr. N-S gr. rd. due W 20'
Old fn cor (W&N) due W 33'

D-9
Fd. tiles & 5/8" X 20" iron rod; add DNR mon & ced post.
16" Beech N30°W 62.4'
11" Maple N25°E 76.0'
11" W Oak S30°W 88.1'
Fn. cor,E-W-N Due S 78'
(in beaver pond)

2
Set 5/8" x 34" re-rod w/RLS cap & ced post w/10c tag.
6" Sug Maple N50°W 9.0'
6" tw sug map N25°E 6.6'
8" sug map in clumps of 3 N60°E 21.4'
E-W fn Due S 44'

SIGNED BY Carl F. Roser 7-17-80 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER (SEAL) LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

HARTWICK TOWNSHIP
OSCEOLA COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET