

Fd 1 McClung Power Pole Wit
Cor is on body of Plat

Cor had been hit by brush hog
& pushed over, straightened
& fit McClung wit