SURVEY & REMONUMENTATION

FEB 1 2 1998

AFATION

SECTION	שווים	CORNER RECORDATION	N CERTIFICATI	E		
For corners in	Hiling	g Requirement of Act 74,	Mich. P.A. 1970			
Osceola	Located In:		İ			•
(County)	Located in:	Corner Code #				
1. Public Land Survey	T <u>19</u> NR <u>F</u> TR_ TR_	BW <u>C-6</u>		PA 34	LAND CORNER 5 OF 1990 la County	
Property Controlling in Section	TR_ S TR_ S TR_			24 Que	les 1997	- 30.
Miscellaneous Property in Sec.	S TR_ S TR_			-filler		ay
Property in Sec.	S IR_			Register of Deed	ds Stamp & File N	Jumber
4. Lot No, Record 5. Private Claims	ded Plat					
			1	ABCDE	FGHIJ	K L
			2	65	4-1-3-2-	- - -
I, Matthew McClung, requirements of P.A. 74, Michigan conformance with regulations and In United States Department of the In that the corner points mentioned in	rules therefore as required interior. Bureau of Land Mark	points mentioned in lines 1 and 2 in the current manual of survey ins	state that under 4 above were in tructions of the	7 8 18 17 18 18 17 18	9 10 11-	12-
Board of Land Surveyors or by	a Decree of a Court of I				13-14-	
terminal and expressed being	JVT		8	19 20	21-22-23-	
NOTE: Not more than 2 come on this certificate.	ers, all in the same town a	and range, may be recorded	9		+	
			10		2826	25-
			11 12-	1 1 1 1	33 - 34 - 35 -	1-1
Hemlock 10"; From 1891 to 1904 program, in which most part, a 3" g at each governmentile per corner, B. Description of corner evident Excavated 1", four	et by deputy post 40.00 ch 76E 6 Lks. S87W 24 Lks. 4 approximate h surveyors T glazed tile f nt set corner placed atop nce found and/or metho	surveyor Sylvest hains from the So ely, Osceola Cour Temple and Trumbu Filled with cinder in the township of each other, od applied in restoring or reest	ter Sibley buth. Ity had a rall, did thers from a continued cablishing corner:	emonumenta le work. Fo forge, wei re suppose on back)	ation or the re placed ed to be 3	
16" cast iron and evidence of tile.	Placed Osc	eola County Monu	Excavated ment 6" be	to 36" fo low surfac	ound no	
C. Description of monument for	corner and accessories	s established to perpetuate loc	ating the position o	of the corner		
Corner C-6. is Os a 1" pipe 18" in 12" Cherry S 17" Cherry S 14" Maple N5	ceola County	Monument, which		rass cap m	MATTHEW A. McCLUNG LAND SURVEYOR	
Signed by Mulhuv T	M' Bling		Date <u>April</u> 1	4, 1997	13037	Strate of the st
Surveyor's Michigan License No.	/130	037		**************************************	THE PROPERTY AND A SECOND SECO	v.

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been entered in the County Surveyor's records.

PA 74: Liber 1, page 425 Sleigh shoe raised with 1/2" rod & cap No. 13037 Dated 15 Mar 1977 10" Maple S50W 47.0° 1 1/4" Pipe West 18.75° Fence Post East 32.0°

Liber 2, page 169 Found Iron & Cap 13037 Dated 15 April 1981 10" Maple S50W 47.0° 1 1/4" Pipe West 18.75° Fence Post East 32.0°

Act 132: Liber 335, page 660 Dated 15 Mar. 1977 Same witnesses shown. Distance of 2,619.96 feet for South 1/2 of section 18.

Hartwick Township Book: Page 1, front pages shows South 1/2 of 17 and 18 to be 2620.0 feet.

Hartwick Township Book: Front Pages, page 3 W. Pine S33W 56.0° Fence Post East 32.00° Shows bearing N1E 2620°.

97 AUG -7 AMII: 57

SURVEY & REMONUMENTATION

FEB 1 2 1998

SECTION