A GURYEY AT TON

NUG 2 3 1995

## LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requireme	ent of Act 74, Mich. P.A. 1	970
Osceola	Located In:	Corner Code ##	
1. Public Land Survey  2. Property Controlling  S.	T R T R	G-8	APPROVED LAND CORNER P.A. 345 OF 1990 Osceola County  19 June 1975 Manthau McDun
in Section S	T R		
			Register of Deeds Stamp & File Number
Property in Sec. S .	тя		
4. Lot No, Record			A B C D E F G H I J K L I
5. Private Claims			2 5 5 7 3 7 2 7 1
Matthew McClung  I,	field survey on	, 19	4
do hereby certify that under requirem in lines 1 and 2 above were in conficurrent manual of survey instructions. Management or by a decree of a Courabove were in conformance with the Court of Law; established, re-estate expressed below:  NOTE: Not more than 4 corners.	ormance with regulations and russ of the United States Department of Law and/or that the corner por rules of the Michigan Board of Laublished, monumented, re-mon	iles therefore as required in the nt of the Interior, Bureau of Land ints mentioned in lines 3, 4 and 9 and Surveyors or by a Decree of 6 umented, recovered, found as	7
on this certificate.			12 31 32 33 34 35 36
Black Ash 18" Black Ash 12" From 1891 to 1904 program, in which most part, a 3" gl at each government tile per corner, p  B. Description of corner eviden Found 1/2" re-rod	by deputy survey st 40.00 chains f N77W 20 Lks. S41E 11 Lks. approximately, Os surveyors Temple azed tile filled set corner in the laced atop of each ce found and/or method app 4" below road sur	ror Sylvester Sib from the South. sceola County had and Trumbull, di with cinders from the township. Ther th other, (continued in restoring or reestablished in restoring or reestablished in restoring or reestablished in restoring or reestablished.	a remonumentation d the work. For the m a forge, were placed e were supposed to be 3 nued on back) shing comer: in center of road and
in Fence line to W			MATTHEW  A. McCLUNG LAND SURVEYOR NO. 13037
C. Description of monument for	· ·		4.16.503.332
a 1" pipe 18" in 1 Treated Gate	ength. Post S20E 142.80 8E 131.5 feet 71.9 feet.	•	3" brass cap mounted on
Signed by Matthew	M Clang	Date_Jun	e 19, 1995
Surveyor's Michigan License No.	13637	For	IM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

OSCEOLA COUNTY REGISTER OF DEEDS

95 JUL -6 AM 10: 40

Mancy Crawford

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records.

I have shown 1 P.A 132 Survey certificate.

This corner is shown in the Hartwick Township book, on pages 46 thru 49.