

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 27 N R 1 E

DESCRIPTION OF CORNER Section corner common to sections 8-9-16-17

CORNER MONUMENT Set DNR Monument

DATE MONUMENT PLACED AND WITNESSED 8-12-69

WITNESSES TO CORNER.....



10" J. Pine N 89 W 34.0

8" J. Pine N 39 E 20.9

AND

10" J. Pine S 24 E 11.7

CIRCLE CORNER REGISTERED

All previously marked.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during project work in this area. Previously established by Marcus Schaaf, from what he identified as U.S. evidence. Two older witnesses face a point about 8' West, but can find no pipe or post. Used more recently by local surveyors. 1½" pipe replaced by DNR monument.

SURVEYOR'S SEAL

SIGNED *Kevin J. Ostling* DATE 8-25-69  
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68