## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		_OSCODA	COUNTY
		T 27N	_N R _1 _E
DESCRIPTION OF CORNER	1/4 corner common to Sec	ctions 8 - 9	
CORNER MONUMENT	Set DNR Monument		<u>.</u> .
DATE MONUMENT PLACED AND WITNESSED 8-12-69			
WITNESSES TO CORNER			
N	10" Oak		20.6
8	<u>8" S. Maple</u> AND	S 32 E	59.6
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement between section corners. No original evidence.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED REGISTERED LAND SURVEYOR 1 1068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing