

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 27 N R 1 E

DESCRIPTION OF CORNER Sec. corner common to Sections 4-5-8-9

CORNER MONUMENT Set DNR Monument

DATE MONUMENT PLACED AND WITNESSED 8-12-69

WITNESSES TO CORNER..... 6" S. Maple N 33 W 56.6'



18" R. Pine N 80 E 45.0'

16" R. Pine S 24 W 83.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry personnel during project work in this area.

Corner previously restored by Marcus Schaaf, and others, from U.S. evidence.

SURVEYOR'S SEAL

SIGNED *Kevin A. Dethling* DATE 8-25-69
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68