

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. _____ N. S., R. _____ E. W.		N89°37'30"W-191.9' FROM B-8
2. PROPERTY CONTROLLING IN SECTION <u>19</u> T. <u>27</u> N. S., R. <u>1</u> E. W.		N89°47'20"E-999.37' FROM B-9 S89°37'30"E-990.8' FROM B-8
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. S., R. _____ E. W.		S89°47'20"W-183.23' FROM B-9
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, KENNETH J. OSTLING, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on MARCH 16,, 1983, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- S89°37'30"E-990.8' FROM B-8 - PROPERTY CORNER SET BY STANDARD SURVEY PROCEDURE.
- N89°47'20"E-999.37' FROM B-9 - PROPERTY CORNER SET BY STANDARD SURVEY PROCEDURE.
- S89°47'20"W-183.23' FROM B-9 - PROPERTY CORNER SET BY STANDARD SURVEY PROCEDURE.
- N89°37'30"W-191.9' FROM B-8 - PROPERTY CORNER SET BY STANDARD SURVEY PROCEDURE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>S89°37'30"E-990.8' FROM B-8</u>	<u>N89°47'20"E-999.37' FROM B-9</u>
5/8" ROD WITH RLS CAP & CEDAR POST	5/8" ROD WITH RLS CAP & CEDAR POST
5" RED OAK S57°W 3.1'	14" RED OAK N20°W 31.4'
4" RED OAK N67°E 11.0'	8" RED OAK S68°E 16.6'

<u>S89°47'20"W-183.23' FROM B-9</u>	<u>N89°37'30"W-191.9' FROM B-8</u>
5/8" ROD WITH RLS CAP AND CEDAR POST	5/8" ROD WITH RLS CAP & CEDAR POST
7" RED OAK N2°W 23.0'	4" RED PINE S81°W 10.0'
6" RED OAK S8°E 39.3'	7" RED OAK S45°E 15.8'

SIGNED BY *Kenneth J. Ostling* DATE 11-9

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

