Cons. 40 47 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 27 N.R. 2 E

			OSCODA	COUNTY
DESCRIPTION OF CORNER _	1/4 corner on N. Sid	e Sec. 5, T27N-R2E		_
CORNER MONUMENT	Set 1½" pipe / concre	te base		
DATE MONUMENT PLACED AR	D WITNESSED <u>5-16-69</u>			
WITHESSES TO CORNER	• •			
N	10" J. Pine	S 50 W	55.8'	
	7" R. Pine	S 80 E	67.1'	<u></u>
CIRCLE CORNER REGISTERED	AND			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established at midpoint between section corners of Sec. 5., on the standard townline. Set corner 17.4' E. of S_k Sec. 32.

SURVEYOR'S SEAL

SIGNED LUITE DE LAND SURVEYON 10068 DATE 6/9/69