## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1, PUBLIC LAND SUPVEY	T. 27 8., R 2.	C-2; C-3; B-3
2. PROPERTY CONTROLL- ING IN SECTION		
3. MISCELLIANEOUS PROPERTY IN SECTION	.T	
4. LOT NO , REC	ORDED PLAT	
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in the re-established, monumented, reland rules therefore as required. Engean of Land Management or and 5 above were, in a field surv	ines 1 and 2 above were, in a monumented, recovered or res in the current manual of surve by a decree of a court of law.	ertify that under requirements of P.A. 74, Michigan P.A. of 1970, field survey on UULY 13,, 1982, established, stored as expressed below and in conformance with regulations y instructions of the United States Department of the Interior, Furthermore, that the corner points mentioned in lines 3, 4, 19, found, recovered, restored, established or re-established dichigan State Board of Registration for Land Surveyors or, by a
ΥΧ <b>ΜΧΧΆΛΚΑΧΧΑΝΜΟΚΟΝΟ</b> C. CONTINUED	?XMXMXXMXXXXXXXXXXXXXX	ХФЖХХЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖЖ
SET 0 6" BL 4" JA	B-3 ONR MONUMENT ACK OAK S4°E : ACK PINE S26°W : WITH TAG SOUTH 15	16.8'
SET CORNER BY SIN COULD LOCATE NO F FOUND METAL FENCE SWAMP CALLS, AND	IGLE PROPORTIONATE PREVIOUS CORNER. E POST AND CEDAR ST IS BEST AVAILABLE	ed in restoring or re-establishing corner:  MEASUREMENT BETWEEN SECTION CORNERS.  TAKE IN MARSH. FITS GOOD TO LAKE 8  EVIDENCE OF CORNER.  EMENT BETWEEN SECTION CORNERS. NO
C-2 T DNR MONUMENT JACK PINE N75°W 2 RED OAK S43°W 4	SET DN 16.4' 9" JAC 12" JA	ished to perpetuate locating the position of the corner:  C=3  NR MONUMENT  CK PINE N55°W 52.8!  ACK PINE S63°W 47.5!
SIGNED BY	TATES AGENCIES:	DATE ////////////////////////////////////
APPROVED AND SIGNED BY	MICHIGAN REGISTERED LAI	DATE
SURVEYOR'S MICHIGAN RE	GISTRATION NO	- · · · · · · OSCODA COUNTY

8 m