MAR 1 9 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

DECUDA COURTY Filing Requirement of Act 74, Mich. P.A. 1970 FILED For corners in Oscoda Located In: Corner Code # 26 NOV 96 3:02 P.M. 27N R 2E PATSY J. PETERS 1. Public Land Survey Т REGISTER OF DEEDS R Т R Т R 2. Property Controlling T R In Section Т R S T R 3. Miscellaneous Register of Deeds Stamp & File Number **Property in Section** _ , Recorded Plat: 4. Lot No. 5. Private Claims Marvin E. Myers _ , in a field survey on June_17 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 comers, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: Guy Veal June 1935 Mon.-Replace Fargo mon. with 6" conc. mon. with brass 32" GLO- Lewis Clason 1839 Mon.-Post WIT: 12" Aspen N63°W 2 Liber 3, pg. 11 Larry G. Beauregard Apr. 1979 Mon.-½" pipe WIT: ½" Bar & Cap West 15.46' Aspen N63°W 21 1ks. dia. tablet
WIT: 6" Elm N38½°E 82 1ks.
2" Thorn tree N66½°W 56 1ks.
Closing corner 0.23 1ks. West 8" W.Pine N32°W 26 1ks. DNR post & tablet 33' North Liber 3, pg. 422 Oct. 5, 1979 Consumers Power Co. Edwin J. McCombs Mon.-Fd. 1" pipe WIT: (old witness tree) Elm N38°E 54.12' 1909 Fargo Eng. Mon.-Iron from stump identified by parol testimony as that of an G.D. Henning Oct. 1943 Mon.-Fd. GLO mon. of original bearing tree Guy Veal B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 3/4" pipe in pavement Found USGLO Conc. Mon. & Brass Cap under pipe Monument box center over USGLO Mon.

Closing corner is West 15.80'(M) 15.18'(R)

And is accepted as a careful and faithful perpetuation of the position of the original corner Standard corner Sections 31 & 32, T27N, R2E

County Remonumentation Nunnumentation Peer Review Group

LIBER

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Found US GLO monument, left in place WIT: DNR post & I.D. location tag & nail E. side NO6°E .32.74° Nail S. side 7" Poplar N66°E 81.62' Nail W. side 7" Poplar S60°W 50.07' Nail W. side DNR location post S36°W 37.14'

position.

TE OF MICHIGANIAN STATE OF MICHIGA **MYERS PROFESSIONAL** SURVEYOR

31600 31600 31600 31600

Signed by >

31600 Surveyor's Michigan License No.

VEVOCIS, JAN. 20, 1871

REVISED MAY 14, 1975 REVISED JAN., 1983