RECTION

LAND CORNER RECORDATION CERTIFICATE Liber 5 pq · 135

For earnors in	Filing F	Requirement of Act 74	I, Mich. P.A. 19	70	1 2 44	. 150
For corners in			1	į	STATE OF MICHI	GAN
OSCODA	Located In: ELMER	Corner Code #			OSCODA COUNT	
(County)					FILED	
1. Public Land Survey	T_27N R2l T R T R	<u>J-5</u>		12 1	ICT 2000 9:12	:02 AM
	ŤR				PATSY J. PETE	
2. Property Controlling	S TR			ŀ	EGISTER OF DE	EUS
in Section 3. Miscellaneous	S TR S TR					
Property in Sec.	S TR					
			L	Register of	Deeds Stamp	& File Number
4 Lot No. Recor	rded Dist					
4. Lot No, Recor	ded Flat			ABCD	EFGH	IJKLN
				2 6 5	4 3-	
				3		
requirements of P.A. 74, Michiga	, in a field surveyon	NE 1 2000 do here	by state that under	4 - 7 - 8	910-	1112
requirements of P.A. 74, Michiga conformance with regulations and	in P.A. of 1970, the corner po	oints mentioned in lines 1 an	d 2 above were in	5		
United States Department of the I	nterior, Bureau of Land Mana	agement or by a decree of a Ci	ourt of Law and /or	6 -18 1	615-	T [
that the corner points mentioned Board of Land Surveyors or by	In lines 3, 4 and 5 above were	e in conformance with the rule	es of the Michigan	7 10 1		
recovered, found as expressed be	low:	AN, COLUMNOTICA, TO-COLUMNOTI	ed, monumented,	8 19 20	21 22	23 24
NOTE: Not more than 2 com	ers, all in the same town ar	nd range, may be recorded		9		
on this certificate.	oro, carri are seine torri ar	id lange, may be recorded		10 30 29	28 27	2625
				11		
				12 31 32	3334_	35 36
				13		
A. Description of original mor	nument and accessories a	and/or subsequent restora	ation:			
l-5 - 1/4 CORNER COMMON TO lov. 1839 - Orig Post set		_				
Pg. 281 Feb. 1973 - Act 132 by N. Feb. 1974 - Act 132 by N. Feb. 1974 - LCRC by N.C. April 1986 - Act 132 by F. Fec. 1986 - Act 132 bt F.	Caldwell, PS#12018 - J. King, PS#25852 - F	Rec. L.1, Pg. 124 - Rec. L.4, Pg. 86 - (3	(3)SOUT - Fnd Conc Mon)SOUTH-Conc Mo	H-33' - Conc Same Info as n (4)5' S of I	Mon Act 132 Rec. N edge Rd (5)	L.1, Pgs 433- In line N-S Fn
						a medical .
B. Description of corner evid		od applied in restoring or re	eestablishing corn	er:	Alexand	MICHICAN
-5 - 1/4 CORNER COMMON TO	SECTIONS 11 & 14					ERICK
Fnd Rec Conc Mon Fnd Witnesses 3 & 4	Pal	PPROVE	2 , 1	0100	* J. K	(ING SSIONAL & O
		nty Remonumenta 'oor Review Group			25 25	io. 852
HIS CORNER APPROVED BY PEE	R REVIEW ON JULY 7, 2	2000, AS THE BEST AVA			. 4444	SSIONAL RIGINAL CORNER
C. Description of monument f		s established to perpetuat	e locating the pos	ition of the corne	r:	
Found Std Oscoda C						
Wit #4 - Corner Is N70 ⁰ E- 56.59' - Se	: -5' South of North e rt S&T South sd 20" Ma	aple		•		
\$20°W - 38.52° - \$	3.00' - Conc Mon - et S&T - West sd of W	est Maple in Tri⊷Map. אest Maple	ed Carsonite Ma le Clump - N5:	arker Post on 5 ⁰ W - 61.54† ·	- Set S&T - N	c. Mon. ortheast sd n Twin Maples
Typical Witness Se	† = 16 - D Spk & 1½" Pl	lastic ID Tag (S&T)				
Signed by 4 redouck	1 Kma		Date <i>Sen</i> a	t. 15, 2000		
Surveyor's Michigan License N	le. 25852					