Surveyor's Michigan License No. 25852

SECTION	LAND CORNER RECORDATION CERTIF	FICATE
For corners in	Filing Requirement of Act 74, Mich. P.A.	1970 Liber 5 pg. 13b
CSCODA (County)	Located In: ELMER Corner Code #	STATE OF MICHIGAN OSCODA COUNTY
1. Public Land Survey	T27N R 2E K-13 T 28N R 2E K-13	FILED 12 OCT 2000 9:13:02 AM
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR S TR	PATSY J. PETERS REGISTER OF DEEDS Register of Deeds Stamp & File Number
4 L-4 No. Depor	ded Diet	
5. Private Claims	, in a field survey on JUNE 2 , 2000 do hereby state that und in P.A. of 1970, the corner points mentioned in lines 1 and 2 above were	A B C D E F G H I J K L 2 6 5 4 3 2 1 1 3 der 4 7 8 9 10 11 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:		the 5 //Or 6 -18 -17 -16 -15 -14 -13 an 7 //Or 6 19 -20 -21 -22 -23 -24
NOTE: Not more than 2 come on this certificate.	ers, all in the same town and range, may be recorded	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
CORNER COMMON TO SECTION 1839 - Orig Post set Pg. 277	nument and accessories and/or subsequent restoration: TIONS 1 & 2 (27-2) AND 35 & 36 (28-2) by William Coon, D.S (1)S37 W-20 lks(13.20')-10"	e as established & set by Schaff in 1934. Desc No Witnesses RECORDED - Fnd DNR Mgn (3)NORTH 15'-E-W To .90' - 4" Oak (8)N77 E-20.1'-8" Birch corner:
Fnd DNR Pipe & Cap in Witnesses Fnd 3, 4, 6	County Review Group 7	FREDERICK J. KING PROFESSIONAL SURVEYOR No. 25852 JAPOFESSIONAL PROFESSIONAL PROFES
HIS CORNER WAS APPROVED BY PEER REVIEW ON JULY 7, 2000, AS THE BEST AVAILABLE EVIDENCE OF THE REESTABLISHMENT OF THE RIGINAL CORNER.		
•	for corner and accessories established to perpetuate locating the	e position of the corner:
	Cap - Placed Carsonite Marker Post - South sd Cor.	- Corner is -15' South of Cal. of E-W 2-Track Trail (Esch Rd.) With #3
Wit #9 - NORTH - 12' Wit #6 - N70 E (R-N6	(R-2.12') - Fnd Rotted off USFS Post (O E & N67 E) - 86.11' (R-85.52' & 86.08') - Set S&T	
Wit #8 =-N70°E -(R-N77°E) - 20.10' - Set S&T above Fnd Tag #15410 -South sd 8" Blrch Wit #7 - SOUTH - 2.90' - Set S&T above Tag #15410 - East sd 4" Oak Wit #4 - N50°W (R-N50°W & N47°W) - 55.30' (R-55.30' & 55.32') Set 9&T above Fnd. Tag *15410~NE sd. 18" Maple		
Typical Witness Set	= 16-D Spk & 1½" Plastic ID Tag (S&T)	
Signed by \\\ \frac{\frac{1}{20000UCK}}{20000UCK}	Date	pept. 15, 2000