RECTION

	LAND CO Filing Re	RNER RECORDATION Requirement of Act 74	ON CERTIFICA . Mich. P.A. 197	TE ham	<u>ل</u> م ا	2 🗇
For corners in	Ū			Liver	5pg 1	2.1
OSCODA (County)	Located in: ELMER	Corner Code #			E OF MICHIGAN CODA COUNTY	[
1. Public Land Survey	T 27N R 2E	_K-2		,	FILED	
·	TR TR TR			12 OCT	2000 9:14:05	AM
Property Controlling in Section Miscellaneous	S TR S T R				SY J. PETERS STER OF DEEDS	
Property in Sec.	S TR			Register of De	eds Stamp & F	ile Number
4. Lot No, Recor	ded Plat					
5. Private Claims				A B C D E	F G H I	J K L
				2 - 6 - 5 -	-43	- 2 1 -
1 FREDERICK KING	5 - 5-14 UND	4		3		
I, FREDER I CK J. KING requirements of P.A. 74, Michiga	n M.A. of 1970, the comer boin	is mentioned in lines 1 and	2 above were in	4 - 7 - 8 - 1	- 91'0	-1112-
conformance with regulations and United States Department of the I	rules therefore as required in the nterior. Bureau of Land Manages	e current manual of survey in	nstructions of the	5		- - -
that the corner points mentioned Board of Land Surveyors or by	in lines 3. 4 and 5 above were in	conformance with the rules	e of the Michigan	6 -18 -17	-1615	-1413-
recovered, found as expressed be	low:	established, re-established	a, monumentea,	8 - 19 - 20	_2122	_2324
NOTE: Not more than 2 corners, all in the same town and range, may be recorded				9		
on this certificate.		0 , , , , , , , , , , , , ,		10-30-29	_2827	_2 6 25
				11		
				12 31 32	_3/33/4	_3536_
A. Description of original mor	nument and accessories and	d/or subsequent restorat	ion:	13		<u> </u>
K- 2 - 1/4 CORNER COMMON TO						
	by William Coon, D.S.	(1)N10°E-23 ks(15.	181) 10" Beach	(2)512 ⁰ W=9 1ka	/5 0413 138 I	Dt
April 1971 - LCRC by N.C. (Caldwell, PS#12018 - Re	c. L.2, Pg. 396 - Se P.	et Std Co. Pipe • Pole (4)S65	& Cap by Sng! E-13.0!- Fence F		
May 19/1 - Act 132 by N.C	Caldwell, PS#12018 -	Rec. L.1. Pgs 8-10	- No Cor Desc.	- No Witnesses		
Feb. 1999 - Field Notes fr (5)N56°E-103.5	62'- 10" Map (6)EAST-2	•0'-Fnc Cor Post ()	RECURDED - Fnd 7)N88 [©] E-93.94!-	Co. Pipe & Cap 7" Man (8)N.F.	-1 OL DND D	
						ICHIICAN
B. Description of corner evid		applied in restoring or rea	establishing corne	n 🆼	STATE OF M	CAL
K-2 - 1/4 CORNER COMMON TO	SECTIONS 1 & 2			1	★/ FREDER	RICK 🔪 🛊 🎙
Fnd Rec. Co. Pipe & C Witnesses - Fnd 3, 5,	·, · · ·	PPROVE	γv	, C 00 =	J. KIN PROFESSIO SURVEY	ONAL E
		nty Romonuments eer Review Grou	ation 295		25852	
THIS CORNER APPROVED BY OF THE POSITION OF THE	PEER REVIEW ON JU	JLY 7, 2000, AS			OFE SSIC STABLISHME	
C. Description of monument for	or corner and accessories es	stablished to perpetuate	locating the nociti	on of the corner		
K-2 - 1/4 CORNER COMMO	ON TO SECTIONS 1 &	2				
Found Rec. Oscod	a County Pipe & Cap -	Corner Is 1.4' W &	0.7' S of Fnc	Cor Post for Fe	nces N & E	
Wit #5 - N50°E - 103 Wit #8 - N60°F - 1.6	n Line with Fnc Cor Pos 3:48' (R-103.52') - Set O' - USFS Post	S&T above Fnd Spk I	Northwest sd 12	2" Maple		Post.
Wit # 6 - N70 E - 2. Wit #7 - N85 E (R-N	.08 ' - 5e t S&T Below Fn 38 E) - 93.86' (R-93.94	d Spk - South sd Fnd ') - Set S&T above I	c Cor Post Fnd Spk North s	ad North Tree -	Tri Maple	
SOUTH - 0.65' - Set	S&T - West sd 4"x6" Tr 35 ⁰ W & West) - 54.17' (eated Fnc Cor Post				e
1/./~/	= 16-D Spk & 14" Plast	ic ID Tag (S&T)				
Signed by \(\frac{\fraccc}\frac{\frac{\frac{\fraccc}\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\f	9. 7) mg 25852 (Date <u>Sept. A</u>	5, 2000		