. Filing Requirement of Act	AND CORNER R 74, Mich. P.A. 1	ECORDATION CERTIF 970	ICATE STATE OF HICHIGAN
For comers in			OSCODA COUNTY
Oscoda Local # (County)	ted in:	Corner Code	FILED
1. Fublic Edita Cuito	<u> </u>	K-7	3 SEP 1999 2:00:01 PH
Sec. T T T	_R _R _R		PATSY J. PETERS REGISTER OF DEEDS
2. Property Controlling S T in Section S T 3. Miscellaneous S T	_R _R _R		Register of Deeds Stamp & File Number
Property in Sec. ST			Liber 5 Page 40
I, Marvin E. Myers, in a field survey or requirements of P.A. 74, Michigan P.A. of 19 2 above were in conformance with regulation manual of survey instructions of the United Land Management or by a decree of a comentioned in lines 3, 4 and 5 above were it Board of Land Surveyors or by a Decree of monumented, recovered, found as express.	ns and rules therefore the states Department of Law and conformance with a Court of Law;	fore as required in the cur ent of the interior, Burea d /or that the corner po ith the rules of the Michi	rent 2 6 5 4 3 2 1 1 1 1 1 2 1 2 1 1 1 2 1 2 1 1 2 1 2 1 1 2 1
NOTE: Not more than 2 corners, be recorded on this certificate.			1Ay 7 8 20 21 22 23 24 9
<ul> <li>A. Description of original monument restoration:</li> <li>K-7 = corner common to Sections 13, 14, 2</li> <li>G.L.O. Nov 1839 W. R. Coon D.S.</li> </ul>	23 & 24. T27N. F	R2E dall Co. Surveyor	1 2 3 1 3 2 3 3 4 3 5 3 6
Mon: Post Wit: 10" Hemlock N12°W 18 lks 14" Hemlock N54°E 7 links  Book 3, Pg. 138 Co. Surveyor records Surveyor and date not given. (Seeley ?)	Mon - Remark of both US bearing was at intersecti Wit: 10" Hemlo	orner. Clearly Identified trees. Comer post was a on of old US section lines	13
Mon - Found Iron stake placed by Randali Wit: Plow Point S45°E 46.7 Plow Point N45°W 46.7	Book 3, Pg. 148 G. D. Henning # Mon – Fd. Iron F By old residents	2240 In claimed to be true Col	July 7, 1955 G. D. Henning # 2240 Mon - Iron Bar (now under 3' road fill) Wit: Plow pt. S45°E 46.7 Plow pt. N45°W 46.7
July 30, 1966 N. C. Caldwell # 12018 Mon – Set %" Bar by reconstruction of Surveys of record MSHD (J.P. Smallwood). Wit: 16" Elm S15"W 80.71	Wit: Plow Pt. S4 Plow Pt. N4	15°E 46.7	L.2, P. 312 LCRC 10, 12, 1970 N. Caldwell #1201 Mon – Found ¾" Bar In pav't
Power Pole N22°E 59.14 Fence Cor. Post \$30°E 47.00	Mon - Found % Wit 16" Elm Power I Fence (	t" Bar 1 S15°W 80.71 Pole N22°E 59.14 Corner S30°E 47.00	Mar 25" Oscoda Co. Road Commission Mon - ½" bar in pav't mon. box Wit: ½" bar N40"W 49.65 ½" bar S50"W 49.65
S55°W 49.69; found MSHD nail & tag in E. Accepted 1/2" bar in pavement monument Standard Oscoda County Cap on 1/2" bar.	enterline Intersect side Utility pole It box as the best	tion of Gerber & Miller Ro 131°E 59.02; found nail & avallable evidence of the	ads; found ½" bar N43°W 49.74; found ½" bar tag in Fence post N07°E 40.48 position of the Original Government Corner. Place
C. Description of monument for come K-7 = comer common to Sections 13, 14 Mon - ½" bar with Standard Oscoda Cou Wit: ½" bar N43°W 49.74 ½" bar S55°W 49.69	. 23. & 24. 14/IV.	ent monument box.	petuate locating the position of the corner:
MSHD nall & tag in E. side Utility Pole Nail & tag in fence post N07°E 40.48	9 N31°E 59.02	DOVED	MARVIN E
	Onunty I	ROVED Remonumentation Review Group	PROFESSIONAL SURVEYOR No.
Ahring Cl		19AUG 95	MARVIN E.  MYERS  PROFESSIONAL SURVEYOR No. 31600 SOFESSIONAL MINIMARIAN MINI
Signed by Surveyor's Michigan License No3	1600	DateA	ugust 14, 1999

.,۲