

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 27 N.R. 3 E


Oscoda COUNTY

DESCRIPTION OF CORNER Section corner common to Section 5-6-7-8

CORNER MONUMENT Set. Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 10/24/68

WITNESSES TO CORNER.....



| | | | |
|-----|-------------------|--------|-------|
| | 16" R. Pine | S 55 E | 51.6' |
| | 5" R. Pine | N 45 W | 38.8' |
| | Center R.R. Grade | East | 31.0' |
| AND | Center R.R. Grade | North | 46.0' |

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this area. Found 1½" iron pipe as reestablished by Seeley in early 1900x from Randall 1886 survey. Believe this to be perpetuation of good corner.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Collins* DATE 11/27/68
REGISTERED LAND SURVEYOR
#10068