MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 27 M.R. 3 E

| | | Oscoda | COUNTY |
|------------------------|------------------------------|-----------|--------|
| DESCRIPTION OF CORNER | 1/4 corner on North Side Sec | ction 6 | |
| CORNER MONUMENT | Set Cons. Dept. Mon. | | |
| DATE MONUMENT PLACED A | ND WITNESSED <u>11/7/68</u> | | |
| WITHESSES TO CORNER | P111 | | |
| | 8" R. Pine | S 85 E | 21.8' |
| _ | 7" W. Pine | S 50 W | 18.7' |
| CIRCLE CORNER REGISTER | AND | , <u></u> | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement between section corners of Section 6. Falls 10.7' east of Sk, Section 31, T28N,R3E.

SURVEYOR'S SEAL

SIGNED LAND SURVEYOR \$10068