SURVEY & REMONUMENTATION

OCT 08 1997

COL	MM	SSIO	N
-----	----	------	---

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Liber 4 Page 175 For corners in Oscoda Located In: Corner Code # (County) STATE OF MICHIGAN OSCODA COUNTY 1. Public Land Survey T27N R 3E D-11 FILED 29 AUG 97 9:02 A.M. T 2. Property Controlling PATSY J. PETERS in Section 3. Miscellaneous REGISTER OF DEEDS Property in Sec. Register of Deeds Stamp & File Number _, Recorded Plat_ 5. Private Claims 1 3 I. Marvin E. Myers, P.S. in a field survey on June 24 , 19<u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 4 conformance with regulations and rules therefore as required in the current manual of survey instructions of the 5 United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and lor that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan 6 Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, 7 recovered, found as expressed below: 8 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 9 on this certificate. 10 Description of original monument and accessories and/or subsequent restoration: GLO - Oct 17,1839, L. Clason, D.S. L. 3, P. 462 F. King, P.S. #25852 July 31, 1984 Mon - Post Mon - Found iron in mon box Wit: 6" Aspen N74°W 7 Lks Wit: In line with N-S Fence South 6" Aspen S74°E 16 Lks In centerline Road **APPROVED** March 1964 N. Caldwell, P.S. #12018 L. 4, P. 441 L. Beauregard, #25852 May 4, 1990 Mon-Not given (Note: Shows cor. Mon: Existing bar in Mon. Box and states that a section subdivision Wit: None given County Remonumentation was made for survey) Peer Review Group LCRC L.2, P374 N. Caldwell, P.S. #12018 Jan, 15, 1971 NCC/IZAUG97 Mon - Found record 1/2 Bar as placed by single proportion. Wit: No references marked Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- Found 12" long cabin spike in mon box in centerline of E-W road infine with fence line South; found nail and tag in E. Side of Utility Pole N30°w 40.35; found ½" bar and cap # 18654 N06°E 33.00; found nail in SE side of fence post N32°E 36.20. Accepted as the best available evidence of the position of the Original Corner. Replaced Cabin Spike in mon box with 5/8"x30" rebar with Standard Oscoda County Cap.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1/2 corner common to Sections 29 & 32, T27N, R3W

Mon- Standard Oscoda County Monument in existing monument box in centerline of E-W paver paver.

1/2" bar & Cap #18654 N05°E 33.00

Spike in West side of Fence Post S10°W 34.18 Spike in East side of Fence Post S33°E 41.52 Spike in West side of Fence Post N32°E 36.20

Surveyor's Michigan License No.



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14,1976 REVISED JAN., 1983 REVISED OCT., 1996