

## OCT 0 8 1997

COMMISSION

## LAND CORNER RECORDATION

For corners in	Filing R	equirement of Act 74	ION CERTIFIC, I, Mich. P.A. 19	70 STATE OF MICHIGAN OSCODA COUNTY
OSCODA (County)	Located In: COMINS TWP.	Comer Code #		FILED
1. Public Land Survey		ż		3 OCT 97 12:44 P.H.
abilo Edila Galivey	T_27NR_3E_ TR TR TR	K-13		PATSY J. PETERS REGISTER OF DEEDS
Property Controlling     in Section     Miscellaneous     Property in Sec.	S T R S T R S T R			LibER 4 Pg. 232
	IR	-		Register of Deeds Stamp & File Number
4. Lot No, Records	ed Plat	,		
5. Private Claims			<del></del>	ABCDEFGHIJKLM
I, FREDERICK 'J. KING requirements of P.A. 74, Michigan I conformance with regulations and rul United States Department of the Inte that the corner points mentioned in Board of Land Surveyors or by a recovered, found as expressed below	les therefore as required in the prior, Bureau of Land Manage lines 3, 4 and 5 above were at the prior of the	ins mentioned in lines 1 and e current manual of survey in ement or by a decree of a Co	l 2 above were in nstructions of the urt of Law and /or	2
	v: s, a∎in the same town and		o, monumented,	8 -19 -20 -21 -22 -23 -24 -9
				10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original monus K-13 - CORNER COMMON TO SE	ECTIONS 35 & 36			13
On File in Reg Cor K-1(26-3) 1 Set 6"x24" Conc	of Deeds Pg. 20.21 Is 6.60' E Mon & Brass Cap on	S220W . New Wit W edge Rd.	JATED BY J. RAN -281 lks (185.4 t Marked N46½0 <sub>M</sub> N07½0E N86½0 <sub>W</sub>	ine - N56 <sup>O</sup> W - 21 lks (13.86') - 11" Pine DALL in 1884 From ORIGINAL BT's 6') Fnd Remains of Randall BT Stump - 107 lks (70.62') - 15" B Oak - 130 lks (85.80') - 15" B. Oak - 128 lks (84.48') - 9" W. Oak
Mar 1974 - Act 132 by N.C. June 1977 - Act 132 by N.C. No Act 74 Found B. Description of corner evidence K-13 - CORNER COMMON TO SE	Recorded for this Coce found and/or method	- No Cor Desc - No - No Cor Desc - No orner applied in restoring or rec	Wit - Rec L. 1	- 59 Tks (44.88') - Cor of Fnc to N &
FOUND GL'O MONUMENT . SOUTH - 40' - USES	& BRASS CAP @ West E			in C.L'. E-W Rd (Cherry Creek Rd)
EAST - 6.76' (M) -	Found GLO MON & BRA	SS CAP @ Cor K-1 (26	;-3) - Road Wor	k has destroyed Old Wit.
		APP	<b>HOVE</b>	D NCC p 7 97  Ition 30 3 6 p 7 9 7
		County F	lemonumenta	ition 2036
This Corner Approved by Cou	nty Peer Review on J	Peer F uly 11, 1997, as a p	Review Group erpetuation of	the Original Government Corner.
C. Description of monument for CK-13 - CORNER COMMON TO SEC	Corner and accessories ex	stablished to perpetuate	locating the position	on of the corner:
GL'O MONUMENT & BRASS	S CAP, with Iron alor	ngside - approx. in	C.L'. gravel roa	ad to W (Cherry Creek) +22' W of C.L'. N-S gravel road (Weaver Rd.)
\$70°E - 64.42' - Sei \$05°W - 40.12' - Sei \$40°W - 42.20' - Coi \$40°W - 76.25' - Sei	t S&T on S side of US t S&T on S side of 19 t S&T on E side of US nc mon @ NE cor of Lo t S&T on NW side of 19 t S&T on E side of 19	STS Red Top Post Dt 22 of "FAIRACRES"	(L'. 3, Pgs 30-	
Signed by <u>Anodouck</u> Surveyor's Michigan License No.	25852 Mag		Date <u>Sep</u> i	<sup>1</sup> . 25, 1997