

OCT Q8 1997

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Libe	R4	ρq.	227
		NTCHTGAN	

For corners in  Oscoda (County)	Located In: Comins Twp.	Corner Code #	OSCODA COUNTY FILED
Public Land Survey	•	M=10	3 OCT 97 12:34 P.H.
1. Fabilio Edita Garvay	T 27N R4E T R T R	A-10 V	PATSY J. PETERS REGISTER OF DEEDS
Property Controlling     in Section	S T R S T R		
3. Miscellaneous	S T R		
Property in Section	S T R		Register of Deeds Stamp & File Number
4. Lot No	, Recorded Plat		ABCDEFGHIJK
5. Private Claims			

I, Larry G. Beauregard , in a field survey on January do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-10 4 corner for Section 25.

Oct. 1839 - Lewis Clason D.S., Set post for corner Section 25. Wit's marked: (Beech 10" \$59° W 10 Links). (Hemlock 24" N 39.5° W 50 Links).

Dan, 1965 - Norman C. Caldwell P.S. #12018 set 3/4" pipe by S.P. method. No wit's marked. (Co. Rd. Comm. survey on Range Jan. 1967 - Norman C. Caldwell P.S. #12018, Fnd. R.R. Spike in pavement. Certificate of Survey. No wit's marked. ( line)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fnd. 2" bar & RLS cap in Mon. box. With no cover. Re-placed with 5/8" x 18" bar & 2" aluminum Re-mon cap.

## **APPROVED**

15EPT 97 County Remonumentation Peer Review Group

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-10	corner	for	Section	25.
t.l_ 1 O	COLUCI	1.01	JCC DIVII	LJ.

5/8" x 18" bar & Oscoda Co. Re-mon cap in Mon. box. Accepted as a careful & faithful establishment of the position of the original corner. Approved by the Peer Group on July 11, 1997. OF MIC

N 85°W 33.10" Cor. Fe. Post. Placed P.K. nail & P.S. ta N 40°W 61.55' 9" Norway. N 85°E 42.0' 9" W.Pine.	LARRY G.
N 68°E 57.02' 18" Maple. Placed 60d spike & P.S. tag #18654 (typ).	BEAUREGAFD SURVEYOR 5 NO. 18654
Signed by <u>fany D.B. Lausegord</u> Surveyor's Michigan License No. 18654	Date    S   G   FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971   REVISED JAN. 1983   REVISED JAN. 1983