## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

							OSCOI	OSCODA		COUNTY	
•						Τ.	28	N	R_	1	<b>E</b>
DESCRIPTION OF CORNER	South 1/4	corner	, Secti	on	30 <b>S</b> EC						
CORNER MONUMENT Set D	.N.R. Monur	nent									
DATE MONUMENT PLACED AND W	ITNESSED		6-26-7	2							
WITNESSES TO CORNER	7" J.	Pine	N	42	W		24.61			_	
N	19" R.	Pine	s	25	W		56.15	,			
**								, · · · <u>- ·</u>			
	AND					·					<del></del> _
CIRCLE CORNER REGISTERE	D										

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set corner by proportionate measurement between section corners. Found stake bottom and NBT stump of Smith corner about 80' north of proper position, but could not justify using this location. Smith notes do not indicate good control for his survey.

, tir	NE OF MICH	
***	KENNETH J. OSTLING LAND	G.
	SURVEYOR RVEYOR! S SE 10068	5.
DI	STRIBUTION:	Ņ

SIGNED	Current & Hilling DATE	7-3-72		
	REGISTERED LAND SURVEYOR 10068			