## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. <u>28</u> N.R. <u>1 E.</u>

		<del>-</del>	Oscoda	COUNTY
DESCRIPTION OF CORNER S	ection corner common to	Sections 32	- 33 on south	boundary of township
CORNER MONUMENT Left 1	1/4" pipe in place			
DATE MONUMENT PLACED AND	WITHESSED August 24,	1962		
VITNESSES TO CORNER				
N .	7* B. Oak	: N 24½ B	127.31	
32	Old NBT 24" R. Pin	ie N 56½ W	90,11	· · · · · · · · · · · · · · · · · · ·
CIRCLE COMPAND DEGLITERS	AND			

## DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in Section 32. Found 1 1/4" pipe at corner as previously established by Randall from U.S. BTs and remarked by C. O. Seeley in 1915. Seeley's NBT still in place. Fence goes south from this corner, but it should by 78 links west.

Closing corner for Sections 4 - 5, T27NR1E is 78 links west.

SURVEYOR'S SEAL

SIGNED Kenneth Joseph DATE September 5, 1962
REGISTERED LAND SURVEYOR