## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. <u>28</u> N.R. <u>1 E.</u>

	Oscoda	COUNTY
DESCRIPTION OF CORNER Section corner common to Section corner	ections 29 - 30 - 31 - 32	
CORNER MONUMENT Set 1" pipe with 4" aluminum cap	0	····
DATE MONUMENT PLACED AND WITNESSED August 27, 19	962	
WITHESSES TO CORNER		
N 7" J. Pine	N 45 W 14.51	<del></del>
7" J. Pine	S 24 <sup>1</sup> / <sub>2</sub> W 15.9'	
AND 7" J. Pine	S 40 <sup>1</sup> / <sub>2</sub> E 17.3'	

## DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey of Section 32. Found very old stake bottom by excavation in general area prescribed by old NBTs SW and N\*ly, which are both down but identifiable. Probably set about the same time as others in this area, since it was noted in a Department survey in 1938.

SURVEYOR'S SEAL

SIGNED Levely Postling DATE September 5, 1962
REGISTERED SAND SURVEYOR