

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 1 E

DESCRIPTION OF CORNER East 1/16 corner on North section line

CORNER MONUMENT Set 4 1/2' of 1" pipe

DATE MONUMENT PLACED AND WITNESSED 6-28-72

WITNESSES TO CORNER..... 7" Cedar N 45 W 10.4'



7" Cedar S 05 W 5.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set by standard procedure for the subdivision of sections, to mark state land boundary.



SIGNED

Kenneth Ostling

DATE

7-5-72

REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

Forestry Division, Lansing